EXAMPLE DATA — FICTIONAL TEST DOCUMENT FOR BATATIS USER TESTING — NOT A REAL PROJECT

SCO Review Queue — 3 Variance Requests (fictional, County of Example)

Each is a condensed Safety Codes Variance Template Part 1 summary as an SCO might receive it. Citations in this file are placeholders: **[ARTICLE-X]** stands in for an article ID so the bundle doesn't assert real code content.

Submission A — VR-2026-031 — Straw-bale workshop

A. Owner: P. Lindqvist; Rep: none; Mailing: Box 12, Example AB; Date: 2026-09-30; signed ✔️
B. Permit # BP-26-118; Legal: NW-12-34-5-W4; Address: RR 3 Example; Description: detached 80 m² workshop with load-bearing straw-bale walls.
C. 2 articles cited [ARTICLE-X], [ARTICLE-Y]; objective, function, intent filled for both (source: registry lookup).
D. Evidence plan: engineer's review letter (attached), test report from accredited lab (attached). Risk assessment: provided · Mitigating measures: provided · Assumptions/limits: provided.

Submission B — VR-2026-034 — Exposed CLT atrium stair

A. Owner: Bowview Commons Ltd.; Rep: R. Mehta; Date: 2026-10-16; signed ✔️
B. Permit # pending; Address: 1200 Example St, Calgary; Description: exposed CLT feature stair open to 3-storey atrium.
C. 3 articles cited, beautifully explained; objective/function/intent filled.
D. 'Fire test to follow.'
Risk assessment: **(blank)** · Mitigating measures: 'sprinklers' · Assumptions/limits: **(blank)**

Submission C — VR-2026-037 — Hempcrete garden suite

A. Owner: **(blank)**; Rep: D. Hartley; Date: **(blank)**; signed ✘
B. Permit #: none; Legal: **(blank)**; Address: 10432 – 79 Ave NW, Edmonton; Description: 60 m² garden suite, 300 mm hempcrete walls, no poly.
C. 2 articles; article 1 complete; article 2 **intent: (blank)**.
D. Manufacturer brochure only.
Risk assessment: short paragraph · Mitigations: listed · Assumptions: 'building is under 3 storeys' (stated as fact; loft not addressed).