



INTERNATIONAL ROV TELEMETRY & PIPELINE INSPECTION LOG

SYSTEM IDENTIFIER: ROV-LOG-PRO-V4 | STANDARDIZATION: IMCA R 004 & ISO 15589-2 / NACE SP0169

1. Survey Operation & Asset Metadata

Asset Name:	24" North Sea Gas Export Interconnector	Survey Vessel:	MV / Deepwater Explorer
Operator:	Global Marine Energy Corp.	ROV System:	Triton-X XL Work Class ROV
Client Name:	fu	Database Origin:	PostgreSQL Telemetry Core
Mission ID:	#34	Geodetic Datum:	WGS 84 / UTM Zone 31N
Video File Ref:	dive_video_01.mp4	Inspection Date:	2026-08-28

2. Engineering Evaluation & Threshold Criteria

CP Potential Window (Ag/AgCl)	Pipeline Health Classification	Engineering Action Directive
-0.85V to -1.15V	FULLY PROTECTED (Healthy)	System at steady state. Continue standard baseline inspection path.
> -0.85V (e.g., -0.74V)	UNDER-PROTECTED (Critical Risk)	Active galvanic corrosion. Log anomaly immediately for sacrificial anode retrofit.
< -1.15V (e.g., -1.24V)	OVER-PROTECTED (Warning)	Risk of Hydrogen Induced Stress Cracking (HISC) and epoxy coating degradation.

3. Integrated Multi-Sensor Telemetry Log Matrix (IMCA Uniform Data Handover)

Timestamp / Video Frame ID	GIS Coordinates (WGS84 Lon/Lat)	Sensor Depth / Sonar Tracking	Traveled Delta (Δ) / Total Cumulative	CP Reading (Potential)	Pipeline Health & Seabed Assessment
11:57:47 - 12:01:51 Frames: #3 to #7152	Lon: 129.084797 E Lat: 35.074823 N	Depth: 91.10 m Sonar: 2.33 m	Δ: +16.0 m Total: 16.0 m	-0.675 V	CRITICAL ANOMALY Under-protected. Active corrosion risk.
12:01:52 - 12:03:42 Frames: #7155 to #10419	Lon: 129.084800 E Lat: 35.074823 N	Depth: 92.76 m Sonar: 0.57 m	Δ: +15.0 m Total: 31.0 m	-0.775 V	CRITICAL ANOMALY Under-protected. Active corrosion risk.
12:03:42 - 12:03:55 Frames: #10422 to #10788	Lon: 129.084954 E Lat: 35.074828 N	Depth: 93.21 m Sonar: 1.22 m	Δ: +0.8 m Total: 31.9 m	-0.675 V	CRITICAL ANOMALY Under-protected. Active corrosion risk.
12:03:55 - 12:04:21 Frames: #10791 to #11541	Lon: 129.084966 E Lat: 35.074825 N	Depth: 93.20 m Sonar: 0.16 m	Δ: +4.7 m Total: 36.5 m	-0.775 V	CRITICAL ANOMALY Under-protected. Active corrosion risk.
12:04:21 - 12:04:35 Frames: #11544 to #11952	Lon: 129.085018 E Lat: 35.074828 N	Depth: 92.93 m Sonar: 1.20 m	Δ: +1.5 m Total: 38.0 m	-0.675 V	CRITICAL ANOMALY Under-protected. Active corrosion risk.
12:04:35 - 12:05:45 Frames: #11955 to #13986	Lon: 129.085029 E Lat: 35.074828 N	Depth: 93.06 m Sonar: 0.85 m	Δ: +6.7 m Total: 44.7 m	-0.950 V	HEALTHY Pipeline stable. Optimal protection.

4. Technical Sign-Off

Lead Offshore Survey Engineer Verification:

Authorized Signature: _____

Date: _____