Macacy Consulting

Pre-Import Machine Inspection Report

⚙ Machine Details

Report ID: MAC-INS: MAC-INJ-2026-026	**Date of Inspection: 12 August 2026**
Case File Reference: MAC-CF-2026-014	**Inspector Name: [redacted]**
Purchase Order Number: [redacted]	**Inspection Location:Factory floor, supplier premises**
Supplier / Factory Name: [redacted]	**Production Supervisor: [redacted]**

1. Container Seal Photo: [Photo 3 Attached] Container doors closed, seal in place, seal number clearly visible.

2. Container & Seal Data

Field	Value
Container Number	MSKU 847293-1
Container Size	40ft HC
Seal Number	CN 884521
Container Condition	Clean, dry, no visible damage
Door Alignment	Correctly closed
Seal Type	Bolt seal, numbered

Inspector's Name: [redacted]

Signature: [redacted]

Date: 12 August 2026

Product Supervisor: [redacted]

Signature:

Date: 12 August 2026

3. Contents Verification

Item	Recorded
Machine model loaded	Injection molding machine, model XYZ-250
Machine serial	XYZ-250-2026-0142
Machine matches PO	✓ Yes
Ancillary items loaded	Control panel, chiller, spare parts kit
Spare parts kit contents verified	✓ Yes (list matches PO)
Packing list matches contents	✓ Yes
No items missing	✓ Yes
No items added beyond PO	✓ Yes
Photographs of contents taken before sealing	✓ Yes (14 photos)
Photographs of container interior	✓ Yes
Moisture absorbent added	✓ Yes
Container floor inspected	✓ Yes — no water, no debris

Macacy Consulting

Inspector's Name: [redacted]

Signature: [redacted]

Date: 12 August 2026

Product Supervisor: [redacted]

Signature:

Date: 12 August 2026

4. Loading & Sealing Process

Step	Result
Container interior inspected before loading	✓ Clean and dry
Loading supervised by inspector	✓ Yes
All items secured for transport	✓ Yes
Container door closed by supplier staff	✓ Yes
Seal applied and photographed	✓ Yes
Seal number written on packing list	✓ Yes
Container moved to port (if applicable)	Not yet — held for payment clearance

Macacy Consulting

5. Verdict — Container Seal
☐ Pass ☐ Hold ☐ Fail

Reason: Container inspected, contents verified, seal applied and photographed. Container held pending motor voltage confirmation (see Report 1). Once confirmed, container is cleared for shipment.

Verification points covered: Points 39 (Witnessed acceptance test), 45 (Pre-shipment inspection scope), 46 (Inspection report before balance payment), 47 (Payment tied to milestones).

6. Attachments
☑ Photo — container door closed
☑ Photo — seal close-up

Inspector's Name: [redacted]

Signature: [redacted]

Date: 12 August 2026

Product Supervisor: [redacted]

Signature:

Date: 12 August 2026

☑ Photo — container number + seal number together
☑ Photo — container interior before loading (4 photos)
☑ Photo — machine loaded and secured (6 photos)
☑ Photo — packing list with seal number written on it
☑ Copy of packing list
☑ Copy of bill of lading (draft)

Inspector signature: [redacted] Date: 12 Aug 2026

Factory representative: [redacted] Date: 12 Aug 2026

Macacy Consulting · hello@macacy.com · +234 703 917 2842
General guidance, not legal advice.

Inspector's Name: [redacted]

Signature: [redacted]

Date: 12 August 2026

Product Supervisor: [redacted]

Signature:

Date: 12 August 2026