V.K architecture Observation point complince tower-09 5th floor Slab Pour 3

VTP REALTY

KARAN BUILDERS
ENGINEERS & CONTRACTORS
Residential | Commercial | Industrial

Checking Date : 02/07/2025	Closing Date : 03/07/2025

Observation Report

VK:a architecture

• SITE VISIT REPORT •

Area - 5000 sq.ft.
concrete - 160 M3

501, 502 Next Gen Avenue
Survey No. 103 Bahiratwadi
Near ICC Trade Tower,
S. B. Road, Pune - 411016
t +91 20 66268888
e mail@vkarch.com
w www.vkarch.com

Project No. & Site Address : 2218, VTP Bellissimo, Mann, pune.

Date : 2/7/25

Name of Site Safety Officer / Engineer / Supervisor
Mr Jitendra B.

Drawing reference if any (Name & No.)
Dwg. No. - 488 (23/11/23)

• Purpose of the Visit :-
To check 1st Floor slab pouring (pour-3)

• If site visit in a form of meeting then points discussed / compliance to previous Report :-
9
[9SW11, 9SW15, 9SW-59, 9SW-54, 9SW11]

• Observations / Current Site Status :-
A) Observation of Area under consideration
- All dimensions for slab Floor light are checked & Found ok as per dwg.
- Near 9SW-11, 9SW-14, 9SW-58, 9SW54 balcony provide cutout on site
- Near SW12 bedroom 3.05 X 3.05 is 3.01 X 3.05 on site.
- Between SW13 & SW14 Bed 3.425 X 3.95 is 3.38 X 3.55 on site.
- Near SW13 balcony sunk 0.05 is 0.03 on site.
- Near SW29 RCC Parch light 1.35 is 0.4 on site.
- dowels bar (NS wall) providing in progress
- shuttering line, level & punch in progress
- cover block fixing in progress
- Lift shafhouse NA.
- All sunk are checked.

• Comments about safety security on site on the day of visit (Mandatory)
- Found ok

• Decisions taken / or corrective actions required if any :-
- permitted for casting after rectification above points in observation by site eng.

• Attendees if any :-
(1) Mr. Nitin G. (VK:a)
(2) Mr. Jitendra B. (VTP)

• If required contact details of individuals to whom above points need to be conveyed :-
To the team

Undertaking :- "We have noted the corrections listed above pertaining to Architectural dimension checking. We assure to carry out those before commencement of Concreting. We also understand that, verification is limited to the correctness of Architectural Dimensions only and no way authenticates any other aspects of construction. We undertake the responsibility for getting reinforcement checking certification from Structural Consultant & full safety of shuttering and centering props, any other construction procedures & supervision.
V.K. a architecture are indemnified against any accidents/failures because of defective shuttering and/or defective construction procedures."

Jitendra 2.7.25

Signature of Representative of Owner / Contractor / Site Safety Officer / Engineer / Supervisor

For VK:a architecture
(a division of VK Design & Projects Private Limited)

Sr. No.	Observation	Location	After Rectification Picture
	Near 9sw-11, 9sw14, 9sw58, 9sw54 balcony provide cutout on site	Slab Pour-3	

	Near sw12 bedroom 3.05*3.05 is 3.01*3.05 on site	Slab Pour-3	

	Between sw13 & sw14 bed 3.425*3.95 is 3.380*3.95 on site.	Slab Pour-3	
	Near sw13 balcony sunk 0.005 is 0.03 on site.	Slab Pour-3	