Vehicle inspection file — bus 4417

Depot: Eastmere. Inspector: Hesper Collingwood.

The following two pages are scans of the workshop sheets. Both carry a page rotation so that they read upright.

Brake test sheet

Front axle: 61%.

Rear axle: 58%.

Parking brake: 24%.

Result: PASS.

Tyre sheet

Tread depth front left: 9 mm.

Tread depth front right: 8 mm.

Tread depth rear left: 6 mm.

Tread depth rear right: 7 mm.

Next inspection due at 182,000 km.