






TUBULAR
SOLUTIONS



TUBULAR
SOLUTIONS

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\006_img.bmp
Datetime: 10/12/2023 11:02:12 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: new guy
Notes: Testing gen report Oct12

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\003_img.bmp
Datetime: 10/12/2023 11:04:34 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: target
Notes: Testing Gen report

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\007_img.bmp
Datetime: 10/12/2023 11:04:58 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: rust
Notes: looks like rust

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\013_img.bmp
Datetime: 10/12/2023 11:05:17 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: dent
Notes: potential dent action here...

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\016_img.bmp
Datetime: 10/12/2023 11:05:37 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: gauling
Notes: looks like some shearing action on this thread.

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\018_img.bmp
Datetime: 10/12/2023 11:05:57 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: debris
Notes: looks like someone left some crap on the pipe again...

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\022_img.bmp
Datetime: 10/12/2023 11:06:22 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: gauling
Notes: severely damaged thread

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\032_img.bmp
Datetime: 10/12/2023 11:07:02 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: gauling
Notes: severe shearing on thread looks like it is rusted over now...

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\007_img.bmp
Datetime: 10/12/2023 11:09:30 AM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: wtf
Notes: seriously you left some shit on the pipe again...

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\044_img.bmp
Datetime: 10/12/2023 12:47:50 PM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: scratch
Notes: hheeeeeee

Image Name: C:\Users\TSI\Desktop\oct-10_bmp\center\025_img.bmp
Datetime: 10/12/2023 1:31:44 PM
Pipe ID: GT690-1001122
Inspector: M. Salamanca
Defect: somethingNEW
Notes: this is a new defect!