

Basic Details

Reporting Location

Project Name	project name
Job No.	job no
Location	location
Visit Date	2018-12-28 07:24:00
Status	Open

Reporter Details

User Name	Super Admin
Email Id	Super Admin
Contact No.	
Designation	admin
Status	Verified

LMRA Check List

#	Working at height	Yes	No	NA	Sevurity
1	Is safe access is provided to reach the working platform?	☒	☐	☐	medium
2	Is working platform is safe to do work?	☐	☒	☐	high
3	If working above 2 mtr level on temporary platform, wear the full body harness?	☐	☒	☐	medium
#	Material lifting	Yes	No	NA	Sevurity
1	Is lifting gears & equipment are physically checked & found fit for lift?	☒	☐	☐	medium
2	Is lifting gears capacity, material weight & CG considered?	☐	☐	☒	high

3	Check the suitability of gantry / supporting column?	☒	☐	☐	high
4	Is lifting lug?	☐	☐	☒	high

LMRA Comments

User	Comment
Super Admin	This my Test Comment On LMRA Id 1
Super Admin	This my test comment by api
Super Admin	asd
Super Admin	This comment test from web
Super Admin	test
Super Admin	Comment from iOS