



TOLL FREE No. : 1800-22-5454  
HELPLINE No. : 022-25987000

Necessary Checkpoints during visit

- Equipment structural damages.
- Equipment paint.
- Safety lights, Accessories Working.
- Oil levels checked.
- Distilled water checked.
- Greasing points.
- Wheel, Bolts.
- Site Inventory check.
- Commissioning check list at the time of commissioning.
- PM Checklist at the time of PM

## Service Job Card

Card No. REN :

**6861**

WO No. :

Date : **11/06/26**

Call Category (Please ✓)

Loading

Unloading

Commissioning

✓ Inspection

Vehicle off Road (BM)

PM

Service Representative Details

1. **Lankesh Meena**

Time In :

**9:46 A**

Time Out :

**12:51 PM**

Company Name : **O where House (Wodehij)**

Contact Person Name & Designation : **Amol Ghodinde**

Contact Number & Email ID : **7057070434**

Asset Code : **40148**

Year of Mfg. : **2014**

Model : **ESW15W**

Hour Meter : **5981.0**

Working Conditions (Please ✓)

Floor Conditions (Please ✓)

✓ Indoor

✓ Outdoor

✓ Super Flat/Epoxy/Trimax

✓ Metal Dust

✓ Chemical Dust

✓ Concrete

✓ Dust

✓ Humidity

✓ Uneven/Metallic Joints

✓ Cold Storage

✓ Standard

✓ Damaged Potholes

Observations of Service Representatives :

**Running time automatics stop (now ok)**

Details of Work Done : **Machine check. Machine running time automatics stop. Machine E-36 show so check and solve. 1 hours machine check again error not show. Machine all function working ok.**

Recommended Spares :

**Glass fuse 1-01 nos**

**V.V.W cable 1-01 set**

Work Status : Completed / Pending

Customer Remarks : **OK**

Service Engineer Name & Sign.

- |                             |
|-----------------------------|
| 1. Customer Copy - White    |
| 2. Office Copy - Pink       |
| 3. Triplicate Copy - Yellow |

Customer Feedback : Satisfied / Not Satisfied

Customer Name & Sign.



TOLL FREE No. : 1800-22-5454  
HELPLINE No. : 022-25987000

Necessary Checkpoints during visit

- Equipment structural damages.
- Equipment paint.
- Safety lights, Accessories Working.
- Oil levels checked.
- Distilled water checked.
- Greasing points.
- Wheel, Bolts.
- Site Inventory check.
- Commissioning check list at the time of commissioning.
- PM Checklist at the time of PM

## Service Job Card

Card No: REN: 1671

WO No.: Date: 12/05/26

Call Category (Please✓)

|            |                       |               |
|------------|-----------------------|---------------|
| Loading    | Unloading             | Commissioning |
| Inspection | Vehicle off Road (BM) | PM            |

Service Representative Details

1. Laxman Singh Time In: 2:00 Time Out: 15:00

Company Name: Godrej Commercial  
Contact Person Name & Designation: Sanjay Todhar  
Contact Number & Email ID: 9921795080

Asset Code: SA 811573 Year of Mfg.: 2014  
Model: WP-3020 Hour Meter: 6053.1

| Working Conditions (Please✓) |               | Floor Conditions (Please✓) |  |
|------------------------------|---------------|----------------------------|--|
| Indoor                       | Outdoor       | Super Flat/Epoxy/Trimax    |  |
| Metal Dust                   | Chemical Dust | Concrete                   |  |
| Dust                         | Humidity      | Uneven/Metallic Joints     |  |
| Cold Storage                 | Standard      | Damaged Potholes           |  |

Observations of Service Representatives:

Error code: 85.7 problem.  
85.7

Details of Work Done:

\* Machine cover removed ok  
check Harnes and all sensor, se ok  
Sensor claiming and porphy fitted ok  
and check all o fancement Machine  
working ok.

Recommended Spares:

Sensor

Work Status: Completed / Pending  
Customer Remarks:

ok, send required  
1 Nos spare of urgent basis.  
AP

Customer Feedback: Satisfied / Not Satisfied

Service Engineer Name & Sign.

Laxman

|                             |
|-----------------------------|
| 1. Customer Copy - White    |
| 2. Office Copy - Pink       |
| 3. Triplicate Copy - Yellow |

Customer Name & Sign.