Audit No.	HSE 5.0-2026-10-26-202	**Client Name**	Dynapac-DC PVT LTD, -New Facility Pune
Audit Name	HSE 5.0	**Auditee Name**	test
Auditor Name	Noor Ahmed	**Region**	West-2
Audit Date	2026-10-26	**Score**	57.14
Location ID	11	**Perform Audit By**	Noor Ahmed

Opening Date	Closing Date	Closing Sign

No Auditee Attendance

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
A.1	Review of Legal Compliance	Is Form B Or Equivanlent Document for Fire Fighting system available?									No attachment
A.2	Review of Legal Compliance	Is Gram panchayat NOC available ? Check for the validity									No attachment
A.3	Review of Legal Compliance	Is CTO license available ? Check the validity									No attachment
A.4	Review of Legal Compliance	Is Form 4 (Haz. Waste Annual return) submitted to PCB ? Check for the records									No attachment
A.5	Review of Legal Compliance	Is Environment Statement i.e. Form 5 Submitted to PCB (for FM dedicated facility) ? Check for the records	YES								No attachment
A.6	Review of Legal Compliance	Is Building Insurance policy available ? Check for the validity									No attachment
A.7	Review of Legal Compliance	Is DG NOC available from Chief Electrical Inspector ?									No attachment
A.8	Review of Legal Compliance	Is Earthing resistance test certificate available ? Check for the validity									No attachment
A.9	Review of Legal Compliance	Is Load test certificate (e.g. F-11 / F-32 etc.) for below Equipments available ? Check for the validity 1.Order Picker . 2.Reach Truck (RT) 3.Fork Lift. 4.BOPT(battery Operate Pallet Truck). 5.HOPT(Hand Operate Pallet truck) 6.VNA 7.Scissor lifts/Boom Lift . 8.Dockleverler . 9.Goods Lift . 10.Stacker . 11. D/BOW shackles ,Belts & Slings . 12.EOT 13.Jib Arm 14.VRC 15.Conveyor (Load bearing certificate)									No attachment
A.10	Review of Legal Compliance	Is Form 13 Pressure vessel certificate available ?If yes, check for the validity									No attachment
A.11	Review of Legal Compliance	Is Forklift driver RTO license available ? If yes, check for the validity									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
A.12	Review of Legal Compliance	Is Environmental test Monitoring report avaialble for below requirements in line with CTO standards . 1.Ambient air for Indoor & outdoor . 2.Water (Drinking water ,Drainage) 3.DG Stack Emmission 4.Noise 5.Lux									No attachment
A.13	Review of Legal Compliance	Is DG stack as per the state legal requirement ? Check for the height ?									No attachment
A.14	Review of Legal Compliance	Is Building Structural Stability certificate available ? Check for the validity									No attachment
A.15	Review of Legal Compliance	Is stability certificate for the fabricated structure (welded) DG stack structure / Slotted angle /Cantilver /Spiral chute available ? if any									No attachment
A.16	Review of Legal Compliance	Is stability certificate of the MTS / HDR /Mezzanine /Mobile storage racks available ? If applicable									No attachment
A.17	Review of Fire Safety System	Review of Fire Safety System									No attachment
A.18	Review of Fire Safety System	Is Fire Hydrant System installed in the facility ?									No attachment
A.19	Review of Fire Safety System	Is fire pump system is on auto mode & pressure in the hydrant system maintained in between 6 Kg/cmÂ² to 8 Kg/cmÂ²?									No attachment
A.20	Review of Fire Safety System	Whether all relevant pumps (Main Pump, Jockey Pump, and Diesel Pump) installed as per the fire noc conditions and are in working condition ?									No attachment
A.21	Review of Fire Safety System	Are all records of tests related to fire detection, alarm system, equipment, fire doors, fire drills, fire maintenance, trainings ... available ?									No attachment
A.22	Review of Fire Safety System	Is AMC available for overall FFS, FAS (Fire Hydrant System, Pump room & Alarm system and other detection system) ?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
A.23	Review of Fire Safety System	Are Fire Hose Cabinets installed and nozzle available with Hose reel?									No attachment
A.24	Review of Fire Safety System	Is Sprinkler System installed in the facility? Type of Sprinkler - K 80 / K 115 / ESFR / In Rack as per the proposed process flow									No attachment
A.25	Review of Fire Safety System	Is Sprinkler installation in line with fire Noc complaince ?									No attachment
A.26	Review of Fire Safety System	Is fire pump room well ventilated, illuminated and emergency lights are available ?									No attachment
A.27	Review of Fire Safety System	Is Sufficient Diesel available(At least 70 % of the tank) in Diesel tank.									No attachment
A.28	Review of Fire Safety System	Is there any leakage in the hydrant, Flanges, valve assembly and joints?									No attachment
A.29	Review of Fire Safety System	What is the capacity of fire water storage tank? Is it as per Fire NOC condition?									No attachment
A.30	Review of Fire Safety System	Provision of secondary containment for diesel storage tank?									No attachment
A.31	Review of Fire Safety System	Is MCP / Beam / FAS Panel installed in the facility?									No attachment
A.32	Review of Fire Safety System	Are smoke detectors installed Under - Office , Mezzanine , MTS ,Chemical room,Scrap area - (if Enclosed) .									No attachment
A.33	Review of Fire Safety System	Is 2 hrs fire rated Push Bar emergency exit doors are available with necessary certificates?									No attachment
A.34	Review of Fire Safety System	Is Sprinkler installed in the Office , MTS and Chemical room are in working condition?									No attachment
A.35	Review of Fire Safety System	Is fire alarm / hooter audible in the entire facility and is periodically checked ? Check for the records									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
A.36	Review of Fire Safety System	Is PA system Installed with adequate power bacup in case power failure or manual siren avaialable .									No attachment
A.37	Review of Fire Safety System	Is adequate number of portable Fire Extinguishers installed in the facility as per the assessment/state norms ? (1 Fire Extinguisher/2000 Sq. ft) and open space i.e. 1/3000 Sq. ft.? 30 m radius									No attachment
A.38	Review of Fire Safety System	Is Fire extinguishers refilled and maintenance done as per the IS2190?									No attachment
B. Review of Fire Safety System											
B.1	Review of Fire Safety System	Is Foam Pourer System or 50 litres mechanical foam fire extinguishers provided, in case of Oil Storage ?									No attachment
B.2	Review of Fire Safety System	All key server /UPS rooms should be protected by fire fighting & Fire detection system e.g. Modular FE , Hydrogen detector etc.?									No attachment
B.3	Review of Fire Safety System	Is Fire fighting team members name displayed in the facility ?									No attachment
B.4	Review of Fire Safety System	Are Fire Safety related signage(Fire Extinguishers, Hydrant etc) is displayed at prominent locations and are visible from anywhere in the warehouse ?									No attachment
B.5	Review of Personal Protective Equipment	Review of Personal Protective Equipment									No attachment
B.6	Review of Personal Protective Equipment	All personal in the facility comply with the site's personal protective equipment requirement i.e. safety shoes, Cut resistance Gloves ,ear plugs,high visibility jacket, helmets ,Chemical handling, Electrical work where applicable?									No attachment
B.7	Review of Personal Protective Equipment	All personnel are using Safety Harnesses for Working at height.? (Applicable For VNA/Order Picker Operation.)									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
B.8	Review of Personal Protective Equipment	Are Signage related to PPE's usage / Matrix and its importance displayed in the facility ?									No attachment
B.9	Review of Personal Protective Equipment	Are PPE's stored in a proper manner as like PPE's stand, PPE's rack, almirah, etc.?									No attachment
B.10	Review of Personal Protective Equipment	Is workers training conducted on the use of PPEs ?									No attachment
B.11	Review of First Aid Facility	Review of First Aid Facility									No attachment
B.12	Review of First Aid Facility	Do we have adequate first aid boxes avialble in the facility @ 1 For every 50 employees									No attachment
B.13	Review of First Aid Facility	Are the required first aid material is checked for the availability and expiry date ?									No attachment
B.14	Review of First Aid Facility	Is first aid register maintained for the first aid given cases with root causes ?									No attachment
B.15	Review of First Aid Facility	Do the list of certified first aider displayed at prominent location in the facility ?									No attachment
B.16	Review of First Aid Facility	Is Wheel chairs/stretcher available in the facility ?									No attachment
B.17	Review of First Aid Facility	Is facility have tie-up with the nearest hospital incase of any medical emergency & also for disposal of biomedical waste generated in our facility ?									No attachment
B.18	Review of Material Stacking and Handling	Review of Material Stacking and Handling									No attachment
B.19	Review of Material Stacking and Handling	Is HDR/MTS/Cantilever/Spiral Chute /Conveyors installed in the facility ?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
B.20	Review of Material Stacking and Handling	Is Safe Working load displayed on the HDR/MTS/Cantilever?									No attachment
B.21	Review of Material Stacking and Handling	Are row guards available in the HDR setup & in Good condition ?									No attachment
B.22	Review of Material Stacking and Handling	Are Up - right guards installed in the HDR system & in Good condition ?									No attachment
B.23	Review of Material Stacking and Handling	Are load beam available & in good condition?									No attachment
B.24	Review of Material Stacking and Handling	Are uprights /Bracings / Row connectors /Safety pins in the HDR Available & observed in good condition ?									No attachment
B.25	Review of Material Stacking and Handling	Are proper grouting bolts provided for the HDR/MTS/Cantilever?									No attachment
C. Review of Material Stacking and Handling											
C.1	Review of Material Stacking and Handling	Is tie beam support provided for single uprights racks ?									No attachment
C.2	Review of Material Stacking and Handling	Is the MTS staircase is properly fixed and handrail is in good condition?									No attachment
C.3	Review of Material Stacking and Handling	Is the MTS Sliding gate is properly fixed and in good condition? If applicable									No attachment
C.4	Review of Material Stacking and Handling	Toe guard for the mezzanine & MTS									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
C.5	Review of Material Stacking and Handling	Is slotted angle racks installed in the facility and is in good condition ?									No attachment
C.6	Review of Material Stacking and Handling	Cargos are properly stacked & secured to avoid tripping and falling (at upper racks) ?									No attachment
C.7	Review of Material Stacking and Handling	Are pallets used for stacking of material are in good condition ?									No attachment
C.8	Review of Material Stacking and Handling	Stacking of material near electrical panels, battery charging stations are maintained distance 3m away ?									No attachment
C.9	Review of Material Stacking and Handling	Distance between material stacked on top of HDR & sprinkler head should be minimum 900mm ?									No attachment
C.10	Review of MHE Operation and Maintenance	Review of MHE Operation and Maintenance									No attachment
C.11	Review of MHE Operation and Maintenance	Is daily/Weekly/Monthly inspection checklist maintained and records of the same are available ?									No attachment
D. Review of MHE Operation and Maintenance											
D.1	Review of MHE Operation and Maintenance	Is MHE PPM being done on Periodically & records available? Check AMC and servicing record with Sampling number...									No attachment
D.2	Review of MHE Operation and Maintenance	Whether dedicated complaint & Key register maintained ?									No attachment
D.3	Review of MHE Operation and Maintenance	Have MHE drivers gone through any Internal / External training ?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
D.4	Review of MHE Operation and Maintenance	Are name of person authorize to drive MHE displayed at the MHE vehicles ?									No attachment
D.5	Review of MHE Operation and Maintenance	Is safe distance maintained between the two MHEs /Safe Working load ?									No attachment
D.6	Review of MHE Operation and Maintenance	Is Speed limit mentioned in the facility ? (5 Km/Hr inside warehouse) and followed by the Operators?									No attachment
D.7	Review of MHE Operation and Maintenance	Is MHE charging area kept isolated and no flammable / combustible material is kept near to the charging area (3 mtr)?									No attachment
E. Review of MHE Operation and Maintenance											
E.1	Review of MHE Operation and Maintenance	Check if any fabricated / Man cage for material picking are strictly prohibited?									No attachment
E.2	Review of MHE Operation and Maintenance	Is portable eye washer available in the MHE charging area ?									No attachment
E.3	Review of Dock Safety	Review of Dock Safety									No attachment
E.4	Review of Dock Safety	Once vehicle lined up to the dock area , vehicle engine should be turned off and vehicle keys should be handover to security / dock person by driver and driver should not sit in the vehicle ?									No attachment
E.5	Review of Dock Safety	Is wheel chocks available and used at the time of loading/unloading process ?									No attachment
E.6	Review of Dock Safety	Is speed limit of 10Km/Hr mentioned outside the facility ?									No attachment
E.7	Review of Dock Safety	Is dock platform/floor in good condition without any damage ?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
E.8	Review of Dock Safety	Is dock bumpers available at each dock and no damaged bumpers observed ?									No attachment
E.9	Review of Dock Safety	Is dock side wall in good condition without any evidence of damage ?									No attachment
E.10	Review of Dock Safety	Is dock railing available and are in good condition ?									No attachment
E.11	Review of Dock Safety	Are the motors of all automatic doors/dock leveller earthed ?									No attachment
E.12	Review of Dock Safety	Are all docks shutters in good condition ?									No attachment
E.13	Review of Dock Safety	Is adequate illumination is available in the yard area ?									No attachment
E.14	Review of Dock Safety	Is focus light available while working at dock area ?									No attachment
E.15	Review of Electrical Safety	Review of Electrical Safety									No attachment
E.16	Review of Electrical Safety	Is SLD updated available /danger notice/signage displayed at all prominent locations as like transformer area/DG area/Electrical panels/DB's ?									No attachment
E.17	Review of Electrical Safety	Is surge protection device is installed at incoming panel									No attachment
E.18	Review of Electrical Safety	Are the electrical installations inspected and repaired by the authorized PWD licensed electrician only ?									No attachment
E.19	Review of Electrical Safety	Are electrical rubber mats conforming to IS 15652 kept under each panel boards ?									No attachment
F. Review of Electrical Safety											
F.1	Review of Electrical Safety	Is proper rated ELCBs/RCCBs are installed at various locations ? And are checked once in 6 month?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
F.2	Review of Electrical Safety	Are the cable above ground supported with proper clamps and conduits/cable tray?									No attachment
F.3	Review of Electrical Safety	Is the hole made for cable entry on panel or wall is sealed properly ?									No attachment
F.4	Review of Electrical Safety	Is the cable gland /routed & identification tags in electrical equipment and panels?									No attachment
F.5	Review of Electrical Safety	Are Panel's / Distribution board's / Inverter batteries properly covered & closed ,such that no current-carrying parts are exposed / visibility of loose connection ?									No attachment
F.6	Review of Electrical Safety	Is it confirmed that no temporary extension boards are used, there are no electrical sockets with multiple plugs and no temporary connections/cable joints ?									No attachment
F.7	Review of Electrical Safety	Is lightning arrester installed in the facility ? resisitance testing report & Earth pits report ?									No attachment
F.8	Review of Electrical Safety	Are the electrical installations freely accessible for operations, inspections and maintenance ?									No attachment
F.9	Review of Electrical Safety	Is there no combustible material present near to the electrical panels ?									No attachment
F.10	Review of Electrical Safety	Is LOTO procedure available for electrical maintenance and strictly followed during electrical maintenance ?									No attachment
F.11	Review of Electrical Safety	Is authorized person to operate main electrical panel displayed near to the panel area ?									No attachment
F.12	Review of Electrical Safety	Is Emergency contact number displayed near to the main electrical panel and UPS rooms (Electrician/Warehouse Manager/ Security supervisor)?									No attachment
F.13	Review of Electrical Safety	Is transformer area barricaded ? If applicable									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
F.14	Review of Electrical Safety	Is fire extinguisher and sand buckets installed near to the Diesel Genset/transformer area ?									No attachment
F.15	Review of Electrical Safety	Is DG set earthed properly i.e. 2 for generator and 2 for body ?									No attachment
F.16	Review of Electrical Safety	Is DG area kept on a proper platform/foundation ?									No attachment
F.17	Review of Electrical Safety	Is DG operating panel kept under shed in order to protect it from rain as well as avoiding electrocution incident ?									No attachment
F.18	Review of Electrical Safety	Is required fire extinguisher installed near to the DG area ?									No attachment
G. Review of Electrical Safety											
G.1	Review of Electrical Safety	The electrical switches installed which may get exposed to rain water should be water resistant like IP-65 rating and properly shedding should be done ?									No attachment
G.2	Review of Electrical Safety	Are all tools periodically inspected and authorized for safe use like a pneumatic stapler, Drill Machine, Grinder etc?									No attachment
G.3	Review of Management of Dangerous Goods (DG) / Hazardous Material	Review of Management of Dangerous Goods (DG) / Hazardous Material									No attachment
G.4	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is hazard communication done as like display of Hazard signage, MSDS for all the hazardous material stored in the facility ?									No attachment
G.5	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is adequate secondary containment provided for the liquid hazardous material ?									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
G.6	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is DG products stored in isolated room with proper smoke detection & fire fighting (sprinkler) system.									No attachment
G.7	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is spill kit available and pictorial chart displayed on how to use a spill kit ?									No attachment
G.8	Review of Management of Dangerous Goods (DG) / Hazardous Material	Are chemicals stored in the facility are as per the compatibility matrix and displayed at prominent location ?									No attachment
G.9	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is Eye Wash station facility or safety shower installed in the facility at prominent location as per the risk assessment ? If required									No attachment
G.10	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is it confirmed that there is no obstruction to the emergency eye wash/ eye shower ?									No attachment
G.11	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is training of the hazardous material handlers conducted timely and records of the same is maintained ?									No attachment
H. Review of Management of Dangerous Goods (DG) / Hazardous Material											
H.1	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is the Compressed gas cylinder stored in a Upright position and secure with the chain? If applicable									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
H.2	Review of Management of Dangerous Goods (DG) / Hazardous Material	Is the Full and empty Compressed gas cylinder store vertical / Upright separately?									No attachment
H.3	Review of Incident Statistics, SQDC, QHSE requirement	Review of Incident Statistics, SQDC, QHSE requirement									No attachment
H.4	Review of Incident Statistics, SQDC, QHSE requirement	Are all accidents and near-miss incidents reported ?									No attachment
H.5	Review of Incident Statistics, SQDC, QHSE requirement	Is recording & investigation of all the cases done to avoid recurrences ?									No attachment
H.6	Review of Incident Statistics, SQDC, QHSE requirement	Have there been no/nil reports of commuting accidents due to non-compliance with the traffic rules?									No attachment
H.7	Review of Incident Statistics, SQDC, QHSE requirement	Is the updated QHSE Policy with Local language display at the Prominent location?									No attachment
H.8	Review of Incident Statistics, SQDC, QHSE requirement	Is the HIRA and Environment Aspect Impact prepared?									No attachment
H.9	Review of Incident Statistics, SQDC, QHSE requirement	Is site safety committee formed?									No attachment
H.10	Review of Incident Statistics, SQDC, QHSE requirement	Are safety posters and other related signage is displayed at prominent locations and are visible from anywhere in the warehouse ?									No attachment
H.11	Review of Housekeeping practices	Review of Housekeeping practices									No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
H.12	Review of Housekeeping practices	Is Condition of Floors and Stairways good for safe material and staff movement?									No attachment
H.13	Review of Housekeeping practices	Is provision of bins for collecting scraps garbage provided?									No attachment
H.14	Review of Housekeeping practices	Is proper aisle marking provided for designate storage areas, clear zone areas or guide traffic.									No attachment
H.15	Review of Housekeeping practices	Is MSDS of housekeeping chemicals available and displayed?									No attachment
H.16	Review of Housekeeping practices	Is Housekeeping staff trained on chemical handling requirement ?									No attachment
H.17	Review of Housekeeping practices	Is housekeeping maintained in good condition ?									No attachment
U.14	Review of Legal Compliance	Review of Legal Compliance									No attachment
U.15	Review of Legal Compliance	Is Factory / Shop license available ? If applicable	NO								No attachment
U.16	Review of Legal Compliance	Is Occupany certificate avaialable ?	NO								No attachment
U.17	Review of Legal Compliance	Environmental clearance (EC), mainly for logistic parks, If Applicable	YES								No attachment
U.18	Review of Legal Compliance	Provisional Fire NOC & review of conditions	YES								No attachment
U.19	Review of Legal Compliance	Requirement of dedicated subleased Fire NOC?	NO								No attachment

Sr.No.	Audit Category	Audit Question	Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount	Remark	Attachment
U.20	Review of Legal Compliance	Is Final Fire NOC Available ? Check the validity	YES								No attachment

Sr. No.			Category			Client Leased	FM Leased	Office	4PL	Distribution Ac-Warehousing & Delivery	Distribution Ac-FTL	4PL - Headcount
Total Selected	A		Review of Legal Compliance			57.14%	0%	0%	0%	0%	0%	0%
	B		Review of Fire Safety System			0%	0%	0%	0%	0%	0%	0%
YES	C		Review of Personal Protective Equipment			0%	0%	0%	0%	0%	0%	0%
	D		Review of First Aid Facility			0%	0%	0%	0%	0%	0%	0%
NO	E		Review of Material Stacking and Handling			0%	0%	0%	0%	0%	0%	0%
	F		Review of MHE Operation and Maintenance			0%	0%	0%	0%	0%	0%	0%
	G		Review of Dock Safety			0%	0%	0%	0%	0%	0%	0%
NA	H		Review of Electrical Safety			0%	0%	0%	0%	0%	0%	0%
	I		Review of Management of Dangerous Goods (DG) / Hazardous Material			0%	0%	0%	0%	0%	0%	0%
Score	J		Review of Incident Statistics, SQDC, QHSE requirement			0%	0%	0%	0%	0%	0%	0%
	K		Review of Housekeeping practices			0%	0%	0%	0%	0%	0%	0%

4		0		0		0		0		0		
3		0		0		0		0		0		
153		160		160		160		160		160		
57.14%		0%		0%		0%		0%		0%		