



http://



# Energy Report

## Best Building: Douro Depot Storage Bldg

**top 9%**

of energy efficiency for this type of  
building in Ontario

**Address:** 713 Warsaw Road

**Building Type:** Storage facilities where equipment or vehicles are  
maintained, repaired or stored

## Worst Building: EMS Lakefield

**bottom 1%**

of energy efficiency for this type of  
building in Ontario

**Address:** 41 Concession Street

**Building Type:** Ambulance stations and associated offices and  
facilities