**Méditerranée Marine Surveyors**

18/05/2026

# Annual condition survey M/Y Aurelia

## Vessel

M/Y Aurelia, 52 m motor yacht, built 2017, flag Cayman Islands, class LR.

### Hull

Hull plating and coating in good condition; minor blistering on starboard quarter to be monitored.

### Machinery

Main engines 2 x 1,940 kW, 11,820 running hours; oil analysis within limits.

### Safety

Liferafts due for service in September 2026; EPIRB battery expiry 10/2026.

## Recommendations

Renew shaft seals at next haul-out; service liferafts before 30/09/2026.

## Machinery details

| Item | Condition | Action |
|---|---|---|
| Port main engine | Good | Routine service at 12,000 h |
| Starboard main engine | Good | Routine service at 12,000 h |
| Generator 1 | Fair | Replace exhaust elbow |
| Generator 2 | Good | None |
| Bilge pumps | Fair | Main pump close to end of life |
| Steering gear | Good | None |

## Electrical

24 V and 230 V systems in good order; shore power connection to be inspected.

## Conclusion

The vessel is in good condition and suitable for its intended use, subject to the recommendations above. Surveyor: J.-M. Castel, Méditerranée Marine Surveyors.

## Scope and method

The survey was carried out afloat at Quai Antoine Ier, Monaco, on 14 and 15 May 2026, then on the hard during a short lift on 16 May 2026, in the presence of the Master and the Chief Engineer. Ultrasonic thickness measurements were taken on the bottom and side shell; machinery was observed running under load.

The survey is a condition survey for the manager and the owner; it is not a class or flag survey and does not replace the statutory certificates.

## Hull – thickness measurements

| Zone | Condition | Min. thickness | Action |
|---|---|---|---|
| Keel plate | Fair | 18.5 mm | No action |
| Bottom fwd P | Fair | 18.7 mm | Monitor |
| Bottom fwd S | Good | 14.7 mm | No action |
| Bottom aft P | Fair | 15.2 mm | No action |
| Bottom aft S | Good | 18.8 mm | Touch-up coating |
| Side shell P | Good | 17.8 mm | Monitor |
| Side shell S | Good | 17.2 mm | No action |
| Transom | Good | 18.2 mm | Touch-up coating |
| Bow thruster tunnel | Fair | 18.2 mm | No action |
| Sea chest 1 | Good | 15.1 mm | No action |
| Sea chest 2 | Good | 18.1 mm | No action |
| Rudder P | Good | 18.3 mm | Touch-up coating |
| Rudder S | Good | 15.4 mm | Touch-up coating |
| Skeg | Good | 15.1 mm | No action |

## Deck and superstructure

Teak deck in fair condition; caulking worn on the aft deck and the flybridge (approximately 18 m of seams). Stainless fittings in good order. Two windows on the main deck show minor delamination of the sealant.

Anchor windlasses and chain lockers in good order; chain marked every 25 m.

## Safety equipment

| Item | Status | Recommendation |
|---|---|---|
| Liferaft 12p A-pack (x2) | Service due 09/2026 | Service before 30/09/2026 |
| EPIRB 406 MHz | Battery expiry 10/2026 | Replace battery and HRU |
| SART (x2) | Valid to 2028 | None |
| Lifejackets SOLAS (x24) | 4 lights inoperative | Replace lights |
| Lifebuoys (x4) | Good | None |
| Fire extinguishers (x18) | 6 due for service | Service or replace |
| Fixed CO2 system engine room | Last test 03/2025 | Test due 03/2027 |
| Fire detection panel | Good | None |
| Pyrotechnics | Expire 11/2026 | Replace |
| Emergency lighting | Good | None |
| Medical chest category A | Inventory partly expired | Restock |

## Photographs

| No. | Subject |
|---|---|
| 1 | Starboard quarter blistering |
| 2 | Port shaft seal |
| 3 | Generator 1 exhaust elbow |
| 4 | Main bilge pump |
| 5 | Aft deck caulking |
| 6 | Liferaft certificates |
| 7 | EPIRB label |
| 8 | Engine room overview |
| 9 | Steering gear |
| 10 | Shore power inlet |
| 11 | Tender cradle |
| 12 | Windlass |

## Recommendations and priorities

| No. | Recommendation | Priority | Before |
|---|---|---|---|
| 1 | Service both liferafts | High | 30/09/2026 |
| 2 | Replace EPIRB battery and HRU | High | 31/10/2026 |
| 3 | Replace main bilge pump (end of life) | High | Next yard |
| 4 | Renew shaft seals | Medium | Next haul-out |
| 5 | Replace generator 1 exhaust elbow | Medium | 31/12/2026 |
| 6 | Re-caulk aft deck seams | Low | Next yard |
| 7 | Replace pyrotechnics | Medium | 30/11/2026 |
| 8 | Restock medical chest | Medium | 30/06/2026 |

## Inspection – Main deck

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Teak deck | Fair | Cosmetic marks |
| Hatches | Good | Minor wear |
| Windows | Good | No defect noted |
| Doors | Fair | Serviced 2025 |
| Handrails | Satisfactory | Monitor |
| Lighting | Good | Minor wear |
| Drainage | Satisfactory | No defect noted |

## Inspection – Upper deck and flybridge

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Hardtop | Satisfactory | No defect noted |
| Helm station | Fair | No defect noted |
| Radar arch | Good | Minor wear |
| Sunbeds | Good | Monitor |
| Bar unit | Good | Minor wear |
| Crane | Fair | Cosmetic marks |

## Inspection – Guest accommodation

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Master cabin | Good | No defect noted |
| VIP cabin | Satisfactory | Cosmetic marks |
| Twin cabin 1 | Satisfactory | Serviced 2025 |
| Twin cabin 2 | Good | Minor wear |
| Bathrooms | Good | No defect noted |
| HVAC | Good | Minor wear |

## Inspection – Crew area and galley

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Crew mess | Satisfactory | Serviced 2025 |
| Crew cabins | Satisfactory | No defect noted |
| Galley equipment | Satisfactory | No defect noted |
| Laundry | Good | No defect noted |
| Cold rooms | Good | No defect noted |

## Inspection – Engine room

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Main engine P | Fair | No defect noted |
| Main engine S | Good | Monitor |
| Gearboxes | Good | No defect noted |
| Generator 1 | Satisfactory | No defect noted |
| Generator 2 | Fair | Serviced 2025 |
| Fuel separators | Satisfactory | No defect noted |
| Bilge system | Fair | Monitor |
| Fire pumps | Good | Serviced 2025 |
| Ventilation | Satisfactory | Monitor |
| Watermakers | Satisfactory | Minor wear |

## Inspection – Steering and propulsion

Visual inspection and function test in the presence of the Chief Engineer.

| Item | Condition | Remarks |
|---|---|---|
| Steering gear | Good | Monitor |
| Rudder stocks | Good | Serviced 2025 |
| Shaft lines | Good | Serviced 2025 |
| Propellers | Good | No defect noted |
| Stabilisers | Good | Serviced 2025 |
| Bow thruster | Good | No defect noted |