

## PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 1054/6-5

Dated: 22-06-2026

It is certified that an inspection team headed by Anand Paswan (Sanitary Inspector)(Name of Officers with designation) from Madhupur Municipal Corporation PHEDinspected the Mahendra Muni Saraswati Shishu Vidya Mandir, Madhupur(Name & Address of the school) on 20/05/2026 (date of inspection) and on the basis ofWater Test Report (Attached) bearing no. TCI 482126000000168F dated 17/08/26of District Level Water Testing Laboratory (PHED Lab) certified thatthe Mahendra Muni Saraswati Shishu Vidya Mandir (Name of school) has safe drinking water

facilities for the students and members of staff of the institution. School is also maintains the

hygienic sanitation condition in the school building &amp; the campus as per norms prescribed by the

Central/ State/ U.T. Govt.

This certificate is valid till 22/06/2027Signature with Seal: (Signature)Name: Anand PaswanDesignation: Sanitary InspectorName & Address of the Office / Department: Madhupur Municipal CorporationTo M.M.S.S.V.M  
College Road, Patharchapti, Madhupur  
(Name & Address of the Institution)कार्यपालक पदाधिकारी  
मधुपुर नगर परिषद

Note: The certificate is to be issued by authorized officer / PHED Lab / local bodies

Gomkumar  
29/9/202629/9/26मदन मोहन मिश्रा  
प्राचार्यमहेंद्र मुनि सरस्वती शिशु-विद्या मंदिर  
बारेली रोड, पथरचाप्टी, मधुपुर