




Vehicle Damage Report








Generated on 2026-05-26 23:02







VEHICLE 2026 Toyota Camry (Silver) — ABC-1234 Category: Sedan	CUSTOMER K Prem Phone: +919345679286 ID / License: 234567
RENTAL PERIOD Start: 2026-05-26 Expected Return: 2026-05-27 Actual Return: —	RESULT SUMMARY Overall: Damage Found Damage count: 1 position(s) New damage detected in 1 position(s). Review the comparison items for details.




Damage Found

New damage detected in 1 position(s). Review the comparison items for details.

POSITION	BEFORE	AFTER	VERDICT	DAMAGE TYPES	AI ASS
Front	 Front-Left Corner Pre-inspection · 0 Clean	 Dashboard Post-inspection · 0 Clean	✓ No Change	—	The and photo differ of the The photo the fr corner vehic the 'A photo the c As th differ a dire comp not p How are n dama provi 'AFT that comp the 'B photo
Front-Left Corner			⚠ New Damage	scratch	A de is vis side

POSITION	BEFORE	AFTER	VERDICT	DAMAGE TYPES	AI ASS
					vehicle AFTER which pres BEF photo scrat appe a new
Left Side			✓ No Change	—	The photo blank view visib or da The photo car's exter evid new Ther indic any dama occu durin renta
Rear-Left Corner			✓ No Change	—	The appe in the cond both with notic dama
Rear		No photo	✓ No Change	—	Posi photo once comp poss
Rear-Right Corner		No photo	✓ No Change	—	Posi photo once comp poss
Right Side		No photo	✓ No Change	—	Posi photo

POSITION	BEFORE	AFTER	VERDICT	DAMAGE TYPES	AI ASS
	 Front-Right Corner Pre-Inspection Clean				once comp poss
Front-Right Corner	 Left Side Pre-Inspection Clean	No photo	✓ No Change	—	Positi photo once comp poss
Roof	 Roof Pre-Inspection Clean	No photo	✓ No Change	—	Positi photo once comp poss
Dashboard	 Trunk Pre-Inspection Clean	No photo	✓ No Change	—	Positi photo once comp poss
Odometer	 Dashboard Pre-Inspection Clean	No photo	✓ No Change	—	Positi photo once comp poss
Front Interior	 Undercarriage Pre-Inspection Clean	No photo	✓ No Change	—	Positi photo once comp poss

POSITION	BEFORE	AFTER	VERDICT	DAMAGE TYPES	AI ASS
Rear Interior	 Left Side Pre-Inspection · 0 Clean	No photo	✓ No Change	—	Posit photo once comp poss
Trunk	 Front-Right Corner Pre-Inspection · 0 Clean	No photo	✓ No Change	—	Posit photo once comp poss
Engine Bay	 Left Side Pre-Inspection · 0 Clean	No photo	✓ No Change	—	Posit photo once comp poss