

ENTRY INVENTORY REPORT

Drawn up jointly · Appendix to the furnished lease

Room 1 · Living room

Walls and ceiling in good condition, recent paint. Oak flooring without notable scratches. Double-glazed window, smooth handle. Radiator in working order. Two power sockets tested, one switch plate slightly yellowed.

Room 2 · Bedroom

Clean carpet, one light mark at the foot of the bed. Sliding wardrobe, rail in good condition. Manual roller shutter working. New bedding under cover, base without play.

Room 3 · Kitchen

Worktop without impact. Stainless sink, clean silicone joint. Two-ring hob and oven tested and working. Refrigerator with freezer, supple door seal. Recirculating hood, new filter.

Room 4 · Shower room

Shower tray without crack, glass screen descaled. Basin unit, one drawer slightly warped. Electric towel rail working. Mechanical ventilation extracting.

Readings

Electricity meter: 045,231 kWh. Cold water meter: 1,208.4 m³. Two sets of keys handed over, including one hall access badge. Overall condition: good, subject to the notes above.