Validation Report

3–5 analytical products: reports, visualizations, alerts

Assessment ID: DA-0005
Timestamp: 00:05
Damage Type: Flood / structural visual change
Severity Classification: Moderate
Change Score: 45.18
Recommended Action: Schedule field validation and monitor closely
Evidence Before Frame: ../data/before_frames/before_0005.jpg
Evidence After Frame: ../data/after_frames/after_0005.jpg

Assessment ID: DA-0010
Timestamp: 00:10
Damage Type: Flood / structural visual change
Severity Classification: Severe
Change Score: 60.77
Recommended Action: Immediate field inspection and emergency response prioritization
Evidence Before Frame: ../data/before_frames/before_0010.jpg
Evidence After Frame: ../data/after_frames/after_0010.jpg



Precision and recall for correlation detection

mestamp_seconds	timestamp	before_frame	after_frame	embedding_similarity	change_score	severity
0	00:00	../data/before_frames/before_0000.jpg	../data/after_frames/after_0000.jpg	0.8314	16.86	Minor
5	00:05	../data/before_frames/before_0005.jpg	../data/after_frames/after_0005.jpg	0.8602	13.98	No Damage
10	00:10	../data/before_frames/before_0010.jpg	../data/after_frames/after_0010.jpg	0.8404	15.96	Minor
15	00:15	../data/before_frames/before_0015.jpg	../data/after_frames/after_0015.jpg	0.8517	14.83	No Damage
20	00:20	../data/before_frames/before_0020.jpg	../data/after_frames/after_0020.jpg	0.8777	12.23	No Damage
25	00:25	../data/before_frames/before_0025.jpg	../data/after_frames/after_0025.jpg	0.8889	11.11	No Damage
30	00:30	../data/before_frames/before_0030.jpg	../data/after_frames/after_0030.jpg	0.8366	16.34	Minor
35	00:35	../data/before_frames/before_0035.jpg	../data/after_frames/after_0035.jpg	0.8680	13.20	No Damage
40	00:40	../data/before_frames/before_0040.jpg	../data/after_frames/after_0040.jpg	0.8607	13.93	No Damage

Performance benchmarks: processing time per video + total data volume analyzed