FieldProof Inspection Report

Demo inspection report. This document is not a compliance certification.

Synthetic Facility Walkthrough

Location: Unit A, Synthetic Facility Plot 7

Inspection ID: 7f6d5c4b-3a29-4817-9e05-0a1b2c3d4e5f

Status: Approved · Version 6

Created: 2026-10-11 15:10 UTC · Last updated: 2026-10-11 15:10 UTC

Reviewer: demo-reviewer · Decision: Approved · Reviewed: 2026-10-11 15:10 UTC · Snapshot version 5

Reviewer comment: Synthetic approval: all required evidence present.

Summary

Checklist items: 3 (passed 0 · failed 0 · not started 3 · n/a 0) · Evidence captured: 3

Checklist and evidence

Item	Status	Evidence	Notes
Emergency exit is unobstructed	Not Started	photo	—
Fire extinguisher is accessible	Not Started	photo	—
General observations	Not Started	note (Synthetic note: dead-leg valve flow-tested, tag FST-0042.)	—