



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila
(632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 20260508-01-RRC

- ☐ Analytical
- ☒ Medical
- ☐ Testing Machine/Big Range
- ☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: PJG ADDRESS: CABANATUAN CITY
SERVICE REQUESTED BY: SIR MANNY DEPARTMENT: RADIOLOGY
EQUIPMENT/MODEL: RADSPEED PRO MC - ER SERIAL NO.: MQ927C1CB002

SERVICE CATEGORY

☐ WARRANTY ☒ CHECKUP/REPAIR ☐ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS _____

COMPLAINT: FILAMENT NOT READY ON X-RAY TUBE

ACTIONS TAKEN

-CHECKED X-RAY TUBE FILAMENT, LARGE FOCAL SPOT HAVE NO CONTINUITY AND RESISTANCE ON THE DMM IS "OL"
MEANING THAT RESISTANCE IS HIGH.
-CHECKED SMALL FOCAL SPOT, OK.
-CHANGED ALL PROTOCOL TO SMALL FOCAL SPOT AND ADVISE END-USERS ON HOW TO EDIT APR.
-X-RAY TUBE IS DEFECTIVE AND IS FOR REPLACEMENT.
-REGISTERED DETECTOR ON THE REPAIRED PC, CALIBRATED DETECTOR, CONFIGURED SETTINGS OF ARUBA, WORKLIST
AND PACS SERVER
-TESTED IMAGE ACQUISITION, OK
-TESTED IMAGE SENDING, OK.
-TESTED STUDY RECEIVING, OK
-TOTAL EXPOSURE COUNT: 341,508
-UNIT IS IN WORKING CONDITION
-ENDORSED TO END-USER

REMARKS/RECOMMENDATIONS

-UNIT IS IN WORKING CONDITION AND FOR PARTS REPLACEMENT

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT
1		0.6/1.2P324DK-85	1	

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
MAY 8, 2026	8AM	7PM	SALES INVOICE
			PURCHASE ORDER

SERVICED BY:


ENGR. RENZ CANO
NAME & SIGNATURE

ACKNOWLEDGED BY:


WILMAR B. CARRERA
NAME & SIGNATURE

CONTACT NO:

EMAIL ADD: rtrtwilmarcarrera@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting