

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: SAN REMIGIO POLYCLINIC ADDRESS: SAN REMIGIO, ANTIQUE
SERVICE REQUESTED BY: END-USER DEPARTMENT: RADIOLOGY
EQUIPMENT/MODEL: RADSPED FIT/DR SERIAL NO.: MP41F0BEC002

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS UNDER WARRANTY

COMPLAINT: PREVENTIVE MAINTENENCE SERVICE WARRANTY (2ND VISIT OF 1ST YEAR) 2/4

ACTIONS TAKEN

-PERFORMED GENERAL CLEANING
-DUST AND SPIDER WEBS ATTACHED TO THE MACHINE WERE VACUUMED AND CLEANED
-TEMPORARILY SET UP THE VIEWWORKS PC AND DETECTOR FOR IMAGE TESTING
-SET UP THE CRADLE CHARGER AND CHARGED THE DETECTOR
-CHECKED BREAKER POWER SUPPLY; 210.5VAC
-CHECKED AVR POWER OUTPUT; 225.8VAC
-PERFORMED TUBE AGING/WARM-UP
-PERFORMED 2 POINTS AND POINT TO POINT CALIBRATION
-TESTED IMAGE AQUISITION; OK
-THE PC, DETECTOR AND CRADLE CHARGER WERE RETURNED TO THE BOX AND SEALED PROPERLY
-REMOVED THE TWO DETECTOR BATTERIES
-THE BOXES AND MACHINE WERE REARRANGED AND COVERED WITH CLING WRAP
-ATTACHED PMS STICKER
-THE CALIBRATION CERTIFICATE WAS SUBMITTED TO THE END USER

REMARKS/RECOMMENDATIONS

THE UNIT IS READY FOR USE / THE FACILITY DOES NOT HAVE A RADTECH TO OPERATE THE X-RAY MACHINE.

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
MAY 8, 2026	11:00 P.M	2:50 P.M	SALES INVOICE
			PURCHASE ORDER
			UNDER WARRANTY

SERVED BY:

JOMARIE T. PENAFLOR

NAME & SIGNATURE

ACKNOWLEDGED BY:

DIANA JEAN M. CABANALAN, MD

NAME & SIGNATURE

CONTACT NO:**EMAIL ADD:**

rhusanrem18@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting