

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: BATAAN GENERAL HOSPITAL AND MEDICAL CENTER ADDRESS: BALANGA CITY, BATAAN
SERVICE REQUESTED BY: SIR GIAN DEPARTMENT: MEDICAL IMAGING
EQUIPMENT/MODEL: MOBILE ART EVOLUTION MX7 SERIAL NO.: MPF16C78B011

SERVICE CATEGORY

☐ WARRANTY ☒ CHECKUP/REPAIR ☐ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: CORRODED AND DAMAGED WHEELS

ACTIONS TAKEN

- EXISTING WHEELS ARE CORRODED AND DAMAGED
- DELIVERED NEW (2) WHEELS FOR UNIT
- DISMANTLED OLD (2) WHEELS
- INSTALLED NEW (2) WHEELS
- UNIT IS IN WORKING CONDITION
- IT IS RECOMMENDED TO AVOID AS MUCH AS POSSIBLE DRIVING UNIT ON ROUGH ROAD/SURFACE TO EXTEND WHEEL LIFE EXPECTANCY OF UNIT
- ENDORSED WASTE MATERIAL (WHEELS) TO BIOMED

REMARKS/RECOMMENDATIONS

- NEW WHEELS ARE INSTALLED. UNIT IS IN WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/07/2026	10 AM	4:30 PM	SALES INVOICE
			PURCHASE ORDER

SERVED BY:

ENGR. MARTEEN CRUZ

NAME & SIGNATURE

ACKNOWLEDGED BY:

GIAN CARLO A. PASAGI/JEFFREY B. MIRANDA/RANDHELLE DY

NAME & SIGNATURE

CONTACT NO:

EMAIL ADD: jhmcdmi@gmail.com/efmsbghmc@gmail.co

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting