

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: DAVAO DOCTORS HOSPITAL - DUMOY

ADDRESS: DAVAO CITY

SERVICE REQUESTED BY:

DEPARTMENT: MOBILE VAN - DUMOY

EQUIPMENT/MODEL: EZYRAD PRO

SERIAL NO.: 3M993BC1B003

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT:

ACTIONS TAKEN

SCHEDULED PREVENTIVE MAINTENANCE UNDER SERVICE CONTRACT - 2ND VISIT

- Checked and cleaned whole unit, changed tapping from 240V to 230V
- Checked and cleaned generator cabinet
- Checked and cleaned boards and fuses
- Checked CMOS battery: good
- Checked mechanical movements, applied WD40
- Checked wire rope: good
- Checked and cleaned xray tube and collimator assy, OK
- Performed x-ray tube calibration for both small and large focus
- Tested xray exposure
- Endorsed to end-user and biomed

It is recommended to provide a 30 kVA AVR to ensure a stable 220V power supply to the unit

REMARKS/RECOMMENDATIONS

UNIT IN WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS

- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/06/2026	9:00AM	10:30AM	SALES INVOICE
			PURCHASE ORDER
			AS PER S.C.

SERVICED BY:


DANIEL N. PINEDA / KENT MONTEVERDE
NAME & SIGNATURE

ACKNOWLEDGED BY:


JONIEL JANSEN TESARA
NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting