

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: GREGORIO MATAS DISTRICT HOSPITAL ADDRESS: KIBLAWAN, DAVAO DEL SUR
SERVICE REQUESTED BY: DEPARTMENT: RADIOLOGY
EQUIPMENT/MODEL: MOBILE ART EVO MX8 VW DR SERIAL NO.: MQ00050E5001

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT:

ACTIONS TAKEN

PERFORMED PREVENTIVE MAINTENANCE SERVICE UNDER WARRANTY

- Checked and cleaned whole unit
- Checked and cleaned x-ray tube & collimator
- Checked and cleaned boards & fuses: OK
- Checked mechanical movements: OK
- Checked wire rope, OK
- Checked 20pcs batteries & CMOS battery, 3.053Vdc
- Checked 9 volt batteries, and tested emergency break release button, OK
- Tested charging of unit, working properly
- Performed x-ray tube calibration (small & large focus): OK
- Performed battery detection & voltage drop: OK
- Checked AVR: OK
- Checked and cleaned DR System: both Acquisition and Reading PC
- Checked and cleaned SCU & FPD: OK
- Tested x-ray exposure and image acquisition: OK
- Verified overall exposure count: 2,318
- Endorsed to end-user

REMARKS/RECOMMENDATIONS

UNIT IN GOOD WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS

- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
02/10/2025	8:30AM	11:30AM	SALES INVOICE
			PURCHASE ORDER
			AS PER WARRANTY

SERVICED BY:

KENT MORRIVERDE
NAME & SIGNATURE

ACKNOWLEDGED BY:

JAN EVANGEL B. RODRIGO, RRT
NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

gmdhradiology@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting