

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: AMAI PAKPAK MEDICAL CENTER ADDRESS: MARAWI CITY
SERVICE REQUESTED BY: DEPARTMENT: ER-XRAY ROOM
EQUIPMENT/MODEL: GEN.RAD.SYSTEM / RADSPED PRO MC DR SERIAL NO.: MQ927C4CB015

SERVICE CATEGORY

☐ WARRANTY ☒ CHECKUP/REPAIR ☐ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: UNUSUAL NOISE DURING EXPOSURE AND ERROR FILAMENT NOT READY

ACTIONS TAKEN

-CHECKED THE UNIT, NO UNUSUAL NOISE DURING EXPOSURE UPON TESTING
-TESTED EXPOSURE, LARGE FOCUS - FILAMENT NOT READY
-TESTED EXPOSURE, SMALL FOCUS - ERROR RADIO OVER CURRENT, ARCING TROUBLE, AND KV UNDER
-CHECKED XRAY TUBE, BUSTED LARGE FOCUS
-CHECKED XRAY TUBE OPENING, OBSERVED GASSY TUBE
-CHECKED INVERTER FUSE AND IGBTs, OK
-CHECKED WAVEFORMS AND VALUES
-CHECKED OTHER FUSES, OK
-CHECKED EXPOSURE COUNT OF THE MACHINE = 131,610 EXPOSURES
-CHECKED DR SYSTEM, ENDORSED TO DELETE OLD PATIENT DATA AND SEND ERROR AT PROCESS VIEWER
-TESTED XRAY EXPOSURE, STILL WITH ERROR
-ENDORSED TO END-USER

REMARKS/RECOMMENDATIONS

-UNIT IS DOWN. FOR REPLACEMENT OF XRAY TUBE. QUOTATION TO FOLLOW.
-UNIT FOR FURTHER EVALUATION AFTER REPLACEMENT OF XRAY TUBE.

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT
		XRAY TUBE, 0.6/1.2P324DK-85	1LOT	

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/07/2026	10:00AM	5:00PM	SALES INVOICE
			PURCHASE ORDER
			AS PER P.O.

SERVICED BY:

JOSEPH REY B. DUMASIG

NAME & SIGNATURE

ACKNOWLEDGED BY:

ANNE B. CEBALLOS

NAME & SIGNATURE

CONTACT NO:

09108232071/09554725759

EMAIL ADD:

anne.ceballos89@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting