

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: SOUTHERN PHILIPPINES MEDICAL CENTER ADDRESS: DAVAO CITY
SERVICE REQUESTED BY: DEPARTMENT: JICA - XRAY ROOM 3
EQUIPMENT/MODEL: GEN. RAD. SYSTEM / RADSPED MF DR SERIAL NO.: MPC5C1678001

SERVICE CATEGORY

☐ WARRANTY ☒ CHECKUP/REPAIR ☐ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: DR SYSTEM ERROR

ACTIONS TAKEN

-CHECKED THE UNIT, DR SYSTEM ERROR OBSERVED - DATABASE ERROR
-RESTARTED THE SOFTWARE, STILL WITH ERROR
-PERFORMED CHECK DATABASE REPAIR TOOL, OK
-CHECKED DATABASE FOLDER, OK
-RESTARTED THE SOFTWARE, OK NO MORE ERROR
-CHECKED NETWORK CONNECTION, STORAGE AND WORKLIST OK
-TESTED IMAGE ACQUISITION, OK
-TESTED IMAGE SENDING, OK
-ENDORSED TO END-USER TO FREE UP SPACE AT WORKLIST/EXAM TAB

REMARKS/RECOMMENDATIONS

-UNIT IN GOOD WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS


☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/01/2026	1:00PM	2:30PM	SALES INVOICE
			PURCHASE ORDER
			SC-CHECKUP

SERVICED BY:


JOSEPH REY B. DUMASIG
NAME & SIGNATURE

ACKNOWLEDGED BY:


ADRIAN RAINE S. POLENTINOS
NAME & SIGNATURE

CONTACT NO:

09950614703

EMAIL ADD:

junaz316pogi@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting