



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila

(632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 20250428-02-KPM

- ☐ Analytical
- ☒ Medical
- ☐ Testing Machine/Big Range
- ☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: DAVAO DOCTORS HOSPITAL - OCC SM ECOLAND ADDRESS: ECOLAND, DAVAO CITY
SERVICE REQUESTED BY: DEPARTMENT: RADIOLOGY
EQUIPMENT/MODEL: RADspeed fit DR SERIAL NO.: MP41EF7BA004

SERVICE CATEGORY

☐ WARRANTY ☒ CHECKUP/REPAIR ☐ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: Cannot create another study due to fullness of the external storage

ACTIONS TAKEN

- Checked DR system, can be seen that the storage is indeed almost full (95%)
- The end-user already knows how to delete past studies and confirmed past studies were already deleted, however, storage is still at 90%
- Checked past studies, checked main folder, database, image, found a folder with large data files
- Confirmed and deleted past files, the storage is now at 47.7%
- Endorsed to end-user

REMARKS/RECOMMENDATIONS

UNIT IN GOOD WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS

- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
- ☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
- ☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
04/28/2026	1:00PM	2:00PM	SALES INVOICE
			PURCHASE ORDER
			S.C.

SERVED BY:

ACKNOWLEDGED BY:

KENT MONTEVERDE
NAME & SIGNATURE

MAE ANN ROSE REYES, RRT
NAME & SIGNATURE

CONTACT NO:

09590745489

EMAIL ADD:

maeannrose.reyes1026@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting