

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: ACE MT. SAMAT MEDICAL CENTER ADDRESS: PILAR, BATAAN
SERVICE REQUESTED BY: DEPARTMENT: RADIOLOGY
EQUIPMENT/MODEL: RADSPED PRO MC SERIAL NO.: MQ927C4D6013

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT:**ACTIONS TAKEN**

- TESTED UNIT BEFORE CONDUCTING PREVENTIVE MAINTENANCE = OK
- CLEANED UNIT
- CHECKED MECHANICAL AND OPERATIONAL MOVEMENTS = OK
- REGREASED HIGH VOLTAGE CABLE ON TUBE SIDE
- PERFORMED FVR CALIBRATION FOR SMALL AND LARGE FOCUS
- TESTED DR SYSTEM = OK
- PERFORMED IMAGE ACQUISITION
- CHECKED COLLIMATOR FUNCTIONS = OK
- CHECKED CONTROL PANEL FUNCTIONS = OK
- CHECKED CONTROL CONSOLE FUNCTIONS = OK
- ADJUSTED CLICK DOG (TRANSVERSAL DIRECTION) FOR ALIGNMENT OF X-RAY TUBE TO BUCKY STAND
- TOTAL EXPOSURE COUNT = 17,434 EXPOSURES
- UNIT IS IN GOOD WORKING CONDITION
- REPORTED ARTIFACT ON SAMPLE IMAGE: UPON CONDUCTING OF PMS, NO ARTIFACTS WERE OBSERVED; THIS CONCERN WILL STILL BE UNDER OBSERVATION AND DETECTOR LOGS ARE COLLECTED FOR REFERENCE

REMARKS/RECOMMENDATIONS

UNIT IS IN WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS

☒ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/06/2026	1:30 PM	6 PM	SALES INVOICE
			PURCHASE ORDER

SERVICED BY:

ENGR. MARTEEN CRUZ

NAME & SIGNATURE

ACKNOWLEDGED BY:

ZERIAN JAY TUGUINAY, RRT

NAME & SIGNATURE

CONTACT NO:

09532966821

EMAIL ADD:

acemtsamat.radiologydept@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting