



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila
 (632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 042926-01-AGM

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: Lucena MMG General Hospital ADDRESS: Lucena, Quezon
 SERVICE REQUESTED BY: PM Contract DEPARTMENT: Radiology
 EQUIPMENT/MODEL: RADspeed MC SERIAL NO.: 3M5262A18009

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: Preventive Maintenance (1/2)

ACTIONS TAKEN

> Checked overall tube exposure count:
 > Checked GSC-2002S console: SN = 1171723510
 - GSC control console is slightly wiggly
 - Adjusted/tightened wall mounting bracket, added 3M heavy duty double sided tape for additional support
 -GSC console mounting is now stable.
 > Checked CH200M
 vertical: ok
 rotation: ok
 telescopic: ok
 wire rope: ok
 > Calibrated unit
 > Thoroughly cleaned unit
 used vacuum
 dismantled fans
 dismantled Inverter/IGBT covers
 > Checked collimator: rotation OK, light: ok, knobs : loose
 > Adjusted/Tightened collimator knobs

REMARKS/RECOMMENDATIONS

Unit is in working condition.

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
04/29/2026			SALES INVOICE
			PURCHASE ORDER

SERVICED BY:

ACKNOWLEDGED BY:

Eng. Alvin Mamangon

MA. PAULINE L. QUITORIANO

NAME & SIGNATURE

NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

Immghradiology1@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting