

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: Lucena MMG General Hospital ADDRESS: Lucena, Quezon
SERVICE REQUESTED BY: PM Contract DEPARTMENT: Radiology/O.R.
EQUIPMENT/MODEL: Opescope Acteno SERIAL NO.: 41D6D8355002

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: Preventive Maintenance (1/2)

ACTIONS TAKEN

> Checked overall tube exposure count:75007
> Calibrated unit
> Calibrated unit's FVR (Filament Voltage Radiography)
> Calibrated unit's FVF (Filament Voltage Fluoroscopy)
> Checked C-arm movements; ok
vertical: ok
forward/backward: ok
pitch and roll: ok
> Checked wheels and brakes: ok
> Lubricated railings

> Checked supply voltage: 232V

> No error encountered.

REMARKS/RECOMMENDATIONS

Unit is in working condition.

SUBMITTED ORIGINAL DOCUMENTS


☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
4/29/2026			SALES INVOICE
			PURCHASE ORDER

SERVED BY:


NAME & SIGNATURE

ACKNOWLEDGED BY:


NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

lmmgghradiology@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting