



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila
(632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 042926-02-AGM

- ☐ Analytical
- ☒ Medical
- ☐ Testing Machine/Big Range
- ☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: Lucena MMG General Hospital ADDRESS: Lucena, Quezon
SERVICE REQUESTED BY: PM Contract DEPARTMENT: Radiology
EQUIPMENT/MODEL: MUX-10 SERIAL NO.: 0362P82704

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT: Preventive Maintenance (1/2)

ACTIONS TAKEN

> Checked collimator
knobs: loose
rotation: ok
light: ok
> Calibrated unit
> Checked column movements:
vertical: ok
telescopic arm: ok
rotation: ok
> Checked brake and driving handle: ok
> Calibrated unit
> Checked overall tube exposure count: 23889
> Lubricated railings and other rusted parts using WD40
> Cleaned unit
> Adjusted/tightened collimator knobs
- Verified that collimator light field no longer auto retracts.

REMARKS/RECOMMENDATIONS

Unit is in working condition.

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
04/29/2026			SALES INVOICE
			PURCHASE ORDER

SERVED BY:

Engr. Alvin Mamangon
NAME & SIGNATURE

ACKNOWLEDGED BY:

MA. PAULINE L. QUITORIANO
NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

Immghradiology1@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting