



SHIMADZU

Philippines Corporation

19F Marajo Tower, 26th St. cor. 4th Ave., BGC, Taguig City 1634 Metro Manila
 (632) 8 869-9563 / (0917) 897-2057 (632) 8 519-9285 spcmanila@shimadzu.com.ph

No. 20260428-1-DA

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: ACE SAN JOSE DEL MONTE MOZUN MEDICAL CENTER ADDRESS: SAN JOSE BULACAN
 SERVICE REQUESTED BY: ABIGAIL T BATACANDOLO DEPARTMENT: RADIOLOGY
 EQUIPMENT/MODEL: MOBIEDART EVOLUTION -MX8 SERIAL NO.: MQ00005BA041

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS

COMPLAINT:

ACTIONS TAKEN

- Verified the charging condition, inspected the wheels and caster wheels, and checked the column and motorized functions for proper operation.
- Verified the proper operation of the hand switch, emergency switch, collimator switch, power assist, and tube rotation.
- Verified the proper operation of the CXDI software and inspected the CXDI?702C detector condition and charger.
- Performed checking and balancing of 20 battery units, with measured voltage ranging from +126.4 to +126.5 VDC. Total number of exposures r
- Conducted X-ray tube aging procedures covering 40 kV to 133 kV at 50 mA to 400 mA for both small and large focus to ensure tube stability an
- Conducted X-ray tube FVR calibration covering 40 kV to 133 kV at 50 mA to 400 mA to ensure accurate exposure performance.
- Verified the X-ray exposure output using a RaySafe radiation meter to ensure accuracy and reliability.
- Verified the collimator alignment using a RaySafe radiation meter to ensure proper X?ray beam alignment.
- Verified DICOM Send and DICOM Modality Worklist (MWM) functionality, and confirmed successful acquisition of DICOM images.
- Performed cleaning of the mobile X?ray unit, including removal of hair and debris from the caster wheels to ensure smooth mobility.

REMARKS/RECOMMENDATIONS

UNIT OPERATIONAL

SUBMITTED ORIGINAL DOCUMENTS

- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
APRIL 28, 2026	11:00PM	2:00PM	SALES INVOICE
			PURCHASE ORDER

SERVICED BY:

ACKNOWLEDGED BY:


 DENNIS MARTIN R. AZORES MARK FELONGCO
 NAME & SIGNATURE


 ABIGAIL T BATACANDOLO
 NAME & SIGNATURE

CONTACT NO:

09772616556 / 09568801805

EMAIL ADD:

sjdmmmc@gmail.com / sian.pcosjdmmmc@

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting