

- ☐
- Analytical
-
- ☒
- Medical
-
- ☐
- Testing Machine/Big Range
-
- ☐
- Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: BICOL REGIONAL HOSPITAL AND MEDICAL CENTER ADDRESS: LEGAZPI CITY
SERVICE REQUESTED BY: _____ DEPARTMENT: RADIOLOGY DEPARTMENT
EQUIPMENT/MODEL: FLEXAVISION F3 WITH CH-200M SERIAL NO.: MPEA63CB7002

SERVICE CATEGORY

☐ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS _____

COMPLAINT: PREVENTIVE MAINTENANCE OF FLEXAVISION F3 WITH CH-200M

ACTIONS TAKEN

1. CLEANED AND CHECKED MECHANICAL MOVEMENTS OF THE SYSTEM
2. RE-GREASED HIGH VOLTAGE CABLES; X-RAY TUBES AND HIGH VOLTAGE GENERATOR SIDES
3. CHECKED PHYSICAL CONDITION OF WIRE ROPE; GOOD
4. PERFORMED FVR ADJUSTMENT OF TUBE 1 AND TUBE 2 BOTH SMALL AND LARGE FOCUS
5. PERFORMED FVF ADJUSTMENT OF TUBE 1 (PULSE FLUOROSCOPY)
6. CHECKED EXPOSURE COUNT; TUBE 1=28140 TUBE 2=56525
7. CHECKED STORAGE AND MWL IN CONNECTION SETTING; PING AND ECHO ARE SUCCESSFUL
8. PERFORMED RADIOGRAPHY AND FLUOROSCOPY EXPOSURE TESTS; GOOD
9. TRANSMITTED SAMPLE IMAGES TO STORAGE; GOOD
10. ENDORSED THE SYSTEM TO END-USER

REMARKS/RECOMMENDATIONS

1. DONE PREVENTIVE MAINTENANCE OF FLEXAVISION F3 WITH CH-200M
2. SYSTEM IS WORKING AND READY TO USE

SUBMITTED ORIGINAL DOCUMENTS

☒ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED
MAY 09, 2026	11AM	3PM

BILLING STATEMENT _____
SALES INVOICE _____
PURCHASE ORDER _____

SERVED BY:

ENGR. JOHN MICHAEL MARFIL
NAME & SIGNATURE

ACKNOWLEDGED BY:

CHRISTIAN ANGELO AMACIO
NAME & SIGNATURE

CONTACT NO: _____
EMAIL ADD: _____