

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: ZONE INTERVENTION MEDICAL AND HOSPITAL, INC ADDRESS: LIGAO CITY, ALBAY
SERVICE REQUESTED BY: _____ DEPARTMENT: X-RAY ROOM
EQUIPMENT/MODEL: MOBILEART ECO MUX-10 SERIAL NO.: 3YCF7FDB006

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☐ INSTALLATION ☐ OTHERS _____

COMPLAINT: PREVENTIVE MAINTENANCE OF MUX-10

ACTIONS TAKEN

1. CLEANED AND CHECKED MECHANICAL MOVEMENTS OF THE SYSTEM; GOOD
2. CHECKED OPERATION OF THE SYSTEM PRIOR PMS
3. PERFORMED TWO-POINT AND POINT-TO-POINT TUBE CURRENT ADJUSTMENTS
4. CHECKED EXPOSURE COUNT; 4455
5. PERFORMED RADIOGRAPHY AND IMAGE ACQUISITION TESTS; GOOD
6. CHECKED POWER SUPPLY OF OUTLETS; MEASURE 193VAC
7. CHANGED TAPPING FROM 220VAC TO 200VAC
8. ENDORSED THE SYSTEM TO END-USER

REMARKS/RECOMMENDATIONS

1. DONE PREVENTIVE MAINTENANCE OF MUX-10
2. SYSTEM IS WORKING AND READY TO USE

SUBMITTED ORIGINAL DOCUMENTS

☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☒ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED

ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT _____
MAY 12, 2026	3PM	4PM	SALES INVOICE _____
			PURCHASE ORDER _____

SERVICED BY:

ACKNOWLEDGED BY:


ENGR. JOHN MICHAEL MARFIL

NAME & SIGNATURE


MARIA EWARY ADONESS

NAME & SIGNATURE

CONTACT NO: _____

EMAIL ADD: _____