

- ☐ Analytical
☒ Medical
☐ Testing Machine/Big Range
☐ Balance

TECHNICAL SERVICE REPORT

CUSTOMER NAME: CARAGA REGIONAL HOSPITAL ADDRESS: SURIGAO CITY
SERVICE REQUESTED BY: DEPARTMENT: OPERATING ROOM 5
EQUIPMENT/MODEL: OPESCOPE ACTENO FD SERIAL NO.: MQD6DBDEA001

SERVICE CATEGORY

☒ WARRANTY ☐ CHECKUP/REPAIR ☒ PREVENTIVE MAINTENANCE ☒ INSTALLATION ☐ OTHERS

COMPLAINT:**ACTIONS TAKEN****SCHEDULED PREVENTIVE MAINTENANCE UNDER WARRANTY - 1ST YEAR, 2ND VISIT**

- Performed test on unit before conducting the maintenance, OK
- Checked and cleaned unit
- Checked mechanical movements
- Checked monitor card and C-arm mobile boards and fuses; OK
- Checked SDR-120 (PC), OK
- Accessed maintenance tool, checked event and error logs
- Checked the sync the date and time settings of the PC and WhaCont
- Performed FVR and FVF calibration of tube
- Verified overall tube exposure = 2,005 total exposures
- Performed FPD calibration
- Tested spot radiography and fluoroscopy exposure, OK
- Tested collimation movements and fluoroscopy save, OK
- Tested thermal printing, OK
- Endorsed to end-user

REMARKS/RECOMMENDATIONS

UNIT IN GOOD WORKING CONDITION

SUBMITTED ORIGINAL DOCUMENTS


- ☐ STICKER ☐ CALIBRATION CERTIFICATE ☐ PM CERTIFICATE ☐ COMPLETION REPORT
☐ SYSTEM CHECK ☐ IQ DOCUMENTS ☐ OQ DOCUMENTS ☐ PM DOCUMENTS
☐ SERVICE REPORT ☐ CALIBRATION DATA (MEDICAL) ☐ INVOICE/BILLING ☐ DELIVERY RECEIPT

PARTS SUPPLIED/RECOMMENDED


ITEM NO.	PART NUMBER	DESCRIPTION	QTY	DELIVERY RECEIPT

DATE OF SERVICE	TIME STARTED	TIME FINISHED	BILLING STATEMENT
05/12/2026	5:00PM	7:00PM	SALES INVOICE
			PURCHASE ORDER
			AS PER W.

SERVICED BY:


D. NOPRE / KENT MONTEVERDE
NAME & SIGNATURE

ACKNOWLEDGED BY:


LANDENDEEFER S. DIVAS, RRT
NAME & SIGNATURE

CONTACT NO:

EMAIL ADD:

crhradiologyfebruary2021@gmail.com

WHITE: Customer Accounting

PINK: SPC Service Dept

GREEN: Customer End User

YELLOW: SPC Accounting