

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_160219_02 LOKASI : AIR RUMBAI

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI RABU, 27 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:01	0.34	0.34	0.34	68.35	68.3	68.4	0	0	0	AMAN
04:30:02	0.34	0.34	0.35	68.33	68.3	68.4	0	0	0	AMAN
05:00:02	0.34	0.34	0.35	68.33	68.3	68.4	0	0	0	AMAN
06:00:01	0.34	0.34	0.34	68.38	68.3	68.4	0	0	0	AMAN
07:00:03	0.34	0.34	0.34	68.42	68.3	68.7	0	0	0	AMAN
08:10:02	0.34	0.34	0.34	68.4	68.4	68.4	0	0	0	AMAN
09:20:00	0.34	0.34	0.34	68.37	68.3	68.4	0	0	0	AMAN
10:00:04	0.34	0.34	0.34	68.4	68.3	68.5	0	0	0	AMAN
11:00:02	0.34	0.34	0.34	68.35	68.3	68.4	0	0	0	AMAN
12:10:02	0.34	0.34	0.34	68.36	68.3	68.4	0	0	0	AMAN
13:00:00	0.34	0.34	0.34	68.36	68.1	68.5	0	0	0	AMAN
14:00:02	0.34	0.34	0.34	68.36	68.2	68.5	0	0	0	AMAN
15:00:04	0.34	0.34	0.34	68.25	68.2	68.3	0	0	0	AMAN
16:10:03	0.35	0.34	0.36	68.17	68.1	68.3	9.6	2	4.8	AMAN
20:50:00	0.35	0.35	0.35	68.1	68.1	68.1	0	0	0	AMAN
21:00:00	0.35	0.35	0.36	68.1	68.1	68.1	0	0	0	AMAN

http://sipalaga.brg.go.id