

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

**KECAMATAN: AIR SUGIHAN** 

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 05 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.04	0.04	0.05	128.64	128.41	128.87	0	0	0	AMAN
01:00:00	0.05	0.05	0.05	129.16	128.87	129.57	0	0	0	AMAN
02:00:00	0.06	0.05	0.06	129.88	129.69	130.04	0	0	0	AMAN
03:00:00	0.06	0.05	0.06	129.71	129.57	129.92	0	0	0	AMAN
04:00:00	0.06	0.05	0.06	129.77	129.69	129.81	0	0	0	AMAN
05:00:00	0.05	0.05	0.05	130.04	129.92	130.16	0	0	0	AMAN
06:00:00	0.05	0.05	0.05	130.38	130.04	131	0	0	0	AMAN
07:00:00	0.05	0.05	0.05	129.92	126.81	131.24	0	0	0	AMAN
08:00:00	0.05	0.05	0.05	128.97	128.75	129.22	0	0	0	AMAN
09:00:00	0.05	0.05	0.05	127.68	127.15	128.29	0	0	0	AMAN
10:00:00	0.06	0.05	0.06	128.1	128.06	128.18	0	0	0	AMAN
11:00:00	0.06	0.06	0.06	128.06	127.95	128.18	0	0	0	AMAN

http://sipalaga.brg.go.id