

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140509_01 LOKASI : KUALA SEPANDUK KECAMATAN : TELUK MERANTI KABUPATEN : PELALAWAN

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 16 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			0
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:07	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
01:00:07	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
02:00:04	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
03:00:07	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
04:00:01	-1.32	-1.33	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
05:10:04	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
06:00:02	-1.32	-1.32	-1.31	11.62	11.6	11.7	0	0	0	BAHAYA
07:00:01	-1.32	-1.33	-1.32	11.62	11.4	11.7	0	0	0	BAHAYA
08:00:08	-1.32	-1.33	-1.32	11.7	11.7	11.7	0	0	0	BAHAYA
09:00:05	-1.33	-1.33	-1.32	11.55	11.4	11.7	0	0	0	BAHAYA
10:00:06	-1.33	-1.33	-1.32	11.45	11.4	11.7	0	0	0	BAHAYA
11:00:21	-1.33	-1.33	-1.33	11.48	11.4	11.7	0	0	0	BAHAYA
12:20:41	-1.32	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA
13:20:14	-1.32	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA
14:10:34	-1.32	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA
15:20:28	-1.33	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA
16:20:08	-1.33	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA
17:10:01	-1.33	-1.33	-1.33	11.5	11.5	11.5	0	0	0	ВАНАҮА
19:50:15	-1.32	-1.32	-1.32	11.7	11.7	11.7	0	0	0	ВАНАҮА
20:00:03	-1.33	-1.33	-1.33	11.7	11.7	11.7	0	0	0	ВАНАҮА
21:20:12	-1.33	-1.33	-1.32	11.7	11.7	11.7	0	0	0	ВАНАҮА
22:00:03	-1.33	-1.33	-1.32	11.6	11.3	11.7	0	0	0	ВАНАҮА
23:00:01	-1.32	-1.33	-1.32	11.5	11.3	11.7	0	0	0	BAHAYA

http://sipalaga.brg.go.id