

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_627104\_02 LOKASI : TN SEBANGAU 2

**KECAMATAN: SABANGAU** 

KABUPATEN: KOTA PALANGKARAYA PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 22 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:10:02	0.65	0.65	0.65	77.1	77.1	77.1	0	0	0	AMAN
02:10:02	0.65	0.65	0.65	77	77	77	0	0	0	AMAN
04:50:01	0.65	0.65	0.65	77	77	77	0	0	0	AMAN
05:40:01	0.65	0.65	0.65	76.9	76.9	76.9	0	0	0	AMAN
06:00:00	0.64	0.64	0.65	77.27	76.9	78	0	0	0	AMAN
07:20:01	0.65	0.65	0.65	77.3	77.3	77.3	0	0	0	AMAN
09:50:02	0.7	0.7	0.7	78.1	78.1	78.1	0	0	0	AMAN
10:10:02	0.7	0.7	0.7	78.07	78	78.1	0	0	0	AMAN
12:40:03	0.7	0.7	0.7	78.1	78.1	78.1	0	0	0	AMAN
17:40:02	0.71	0.71	0.71	77.8	77.8	77.8	0	0	0	AMAN
18:10:03	0.7	0.7	0.71	77	77	77	0	0	0	AMAN
19:00:03	0.71	0.71	0.71	77.9	77.7	78.1	0	0	0	AMAN
20:40:03	0.71	0.71	0.71	77.85	77.7	78	0	0	0	AMAN
21:40:04	0.71	0.71	0.72	77.8	77.6	78	0	0	0	AMAN

http://sipalaga.brg.go.id