

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : MUBA2
LOKASI : KEPAYANG
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI RABU, 20 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.43	-4.42	-4.44	44.33	42.39	46.5	0	0	0	BAHAYA
01:00:00	-4.44	-4.41	-4.46	42.67	40.08	46.4	0.5	0	0.5	BAHAYA
02:00:00	-4.43	-4.41	-4.45	45.34	40.99	48.66	0	0	0	BAHAYA
03:00:00	-4.41	-4.4	-4.43	53.28	48.9	56.08	1	0	0.5	BAHAYA
04:00:00	-4.42	-4.41	-4.44	50.42	45.43	58.02	2	0	0.5	BAHAYA
05:00:00	-4.43	-4.42	-4.44	49.27	46.7	51.27	0.5	0	0.5	BAHAYA
06:00:00	-4.42	-4.41	-4.43	51.46	49.44	55.41	0	0	0	BAHAYA
07:00:00	-4.43	-4.41	-4.44	50.27	47.14	54.13	0	0	0	BAHAYA
08:00:00	-4.46	-4.46	-4.48	47.68	45.59	49.86	0	0	0	BAHAYA
09:00:00	-4.47	-4.46	-4.48	48.94	45.86	53.08	0	0	0	BAHAYA
10:00:00	-4.47	-4.47	-4.49	47.32	46.1	50.06	0	0	0	BAHAYA
11:00:00	-4.49	-4.48	-4.49	43.82	40.44	46.7	0	0	0	BAHAYA
12:00:00	-4.49	-4.48	-4.5	41.43	39.47	44	0	0	0	BAHAYA
13:00:00	-4.49	-4.48	-4.5	39.99	37.37	43.48	0	0	0	BAHAYA
14:00:00	-4.47	-4.47	-4.47	43.21	43.21	43.21	0	0	0	BAHAYA

http://sipalaga.brg.go.id