

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_150710\_03 LOKASI : PARIT CULUM II KECAMATAN : SABAK BARAT

KABUPATEN: TANJUNG JABUNG TIMUR

PROVINSI : JAMBI

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:01	0.02	0.02	0.02	71.15	71.1	71.2	0	0	0	AMAN
01:00:30	0.02	0.02	0.02	71.1	71.1	71.1	0	0	0	AMAN
02:00:05	0.02	0.02	0.02	71.1	71.1	71.1	0	0	0	AMAN
03:00:03	0.02	0.02	0.02	71.1	71.1	71.1	0	0	0	AMAN
05:00:09	0.01	0.01	0.01	71.7	71.7	71.7	0	0	0	AMAN
11:30:04	-0.02	-0.02	-0.01	71.7	71.7	71.7	0	0	0	SIAGA
12:00:05	-0.02	-0.03	-0.02	71.8	71.8	71.8	0	0	0	SIAGA
13:00:06	-0.03	-0.03	-0.02	71.55	71.5	71.6	0	0	0	SIAGA
14:00:02	-0.03	-0.03	-0.02	71.57	71.3	71.7	0	0	0	SIAGA
15:00:01	-0.03	-0.03	-0.02	71	70.9	71.3	0	0	0	SIAGA
16:00:00	-0.03	-0.03	-0.03	71	71	71	0	0	0	SIAGA
17:00:01	-0.04	-0.05	-0.03	71.25	71.1	71.4	0	0	0	SIAGA
18:00:01	-0.04	-0.05	-0.03	71.15	71.1	71.4	0	0	0	SIAGA
19:00:05	-0.04	-0.04	-0.04	71.12	71.1	71.2	0	0	0	SIAGA
20:00:01	-0.04	-0.05	-0.04	71.12	70.8	71.2	0	0	0	SIAGA
21:00:02	-0.05	-0.05	-0.04	71.13	70.8	71.2	0	0	0	SIAGA
22:00:02	-0.05	-0.06	-0.04	71.1	71.1	71.1	0	0	0	SIAGA
23:00:02	-0.05	-0.05	-0.05	71	70.8	71.1	0	0	0	SIAGA

http://sipalaga.brg.go.id