

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : LUMPUR2

LOKASI: PS1-SEBOKOR, PADANG SUGIHAN

KECAMATAN: AIR SUGIHAN

KABUPATEN: OGAN KOMERING ILIR PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 01 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.04	0.04	0.04	126.76	126.37	126.93	0	0	0	AMAN
01:00:00	0.04	0.04	0.04	126.74	126.37	127.04	0	0	0	AMAN
02:00:00	0.04	0.04	0.04	126.95	126.59	127.26	0	0	0	AMAN
03:00:00	0.04	0.04	0.04	127.02	126.7	127.15	0	0	0	AMAN
04:00:00	0.03	0.02	0.03	127.19	127.04	127.26	0	0	0	AMAN
05:00:00	0.03	0.03	0.03	127.4	127.15	127.72	0	0	0	AMAN
06:00:00	0.03	0.03	0.03	127.55	127.26	127.83	0	0	0	AMAN
07:00:00	0.03	0.03	0.03	128.04	127.95	128.18	0	0	0	AMAN
08:00:00	0.03	0.03	0.04	128.79	128.41	129.22	0	0	0	AMAN
09:20:00	0.04	0.04	0.04	130.41	128.99	134.97	0	0	0	AMAN
10:00:00	0.04	0.04	0.04	128.22	125.7	137.44	0	0	0	AMAN
11:00:00	0.04	0.04	0.04	128.06	127.72	128.64	0	0	0	AMAN
12:00:00	0.04	0.04	0.04	127.83	127.72	127.95	0	0	0	AMAN

http://sipalaga.brg.go.id