

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621103_06 LOKASI : BUKIT LITI 3

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:20:04	-0.04	-0.05	-0.04	64.4	64.4	64.4	0	0	0	SIAGA
01:00:02	-0.04	-0.04	-0.04	64.4	64.4	64.4	0	0	0	SIAGA
02:00:01	-0.04	-0.05	-0.04	64.3	64.3	64.3	0	0	0	SIAGA
03:20:01	-0.04	-0.04	-0.04	64.3	64.3	64.3	0	0	0	SIAGA
05:00:00	-0.05	-0.05	-0.04	64.3	64.3	64.3	0	0	0	SIAGA
12:00:00	-0.05	-0.05	-0.05	64.3	64.2	64.5	0	0	0	SIAGA
13:10:02	-0.05	-0.05	-0.05	64.3	64.3	64.3	0	0	0	SIAGA
14:00:01	-0.06	-0.06	-0.05	64.3	64.2	64.4	0	0	0	SIAGA
15:00:04	-0.06	-0.06	-0.05	64.33	64.1	64.4	0	0	0	SIAGA
16:00:03	-0.06	-0.06	-0.05	64.2	64.2	64.2	0	0	0	SIAGA
17:00:00	-0.06	-0.06	-0.06	64.18	64.1	64.2	0	0	0	SIAGA
18:00:00	-0.06	-0.06	-0.05	64.15	64.1	64.2	0	0	0	SIAGA
19:10:04	-0.06	-0.06	-0.06	64.1	64.1	64.1	0	0	0	SIAGA
20:00:03	-0.05	-0.06	-0.05	64.28	64.1	64.8	6	0	4.4	SIAGA
21:10:02	-0.04	-0.04	-0.04	64.2	64.2	64.2	0	0	0	SIAGA
22:40:00	-0.03	-0.03	-0.03	64.2	64.2	64.2	0.2	0	0.2	SIAGA
23:00:01	-0.03	-0.04	-0.03	64.2	64.2	64.2	0.2	0	0.2	SIAGA

http://sipalaga.brg.go.id