

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621101_02

LOKASI : DANDANG
KECAMATAN : PANDIH BATU
KABUPATEN : PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
01:30:35	0.05	0.05	0.05	81.2	81.2	81.2	0	0	0	AMAN
02:10:09	0.05	0.05	0.05	81.6	81.6	81.6	0	0	0	AMAN
03:10:07	0.05	0.04	0.05	81.5	81.5	81.5	0	0	0	AMAN
05:00:25	0.04	0.04	0.04	81.3	81.3	81.3	0	0	0	AMAN
11:30:01	0.04	0.04	0.04	80.4	80.3	80.5	0	0	0	AMAN
12:10:37	0.04	0.04	0.04	80.2	80.2	80.2	0	0	0	AMAN
14:50:06	0.03	0.03	0.03	79	79	79	0	0	0	AMAN
15:10:05	0.04	0.03	0.04	79.2	79.1	79.3	0	0	0	AMAN
16:00:02	0.04	0.04	0.04	79.2	78.9	79.5	0	0	0	AMAN
17:00:18	0.04	0.03	0.04	79.4	79.1	79.9	2.2	0	2	AMAN
18:00:05	0.04	0.03	0.04	79.75	79.3	80	0.2	0	0.2	AMAN
19:00:05	0.04	0.03	0.04	80.23	80.1	80.5	6.8	0	2	AMAN
20:00:07	0.03	0.03	0.04	80.52	80.3	80.8	3.4	0	1	AMAN
21:00:01	0.04	0.04	0.04	80.73	80.5	81	0.8	0	0.6	AMAN
22:00:02	0.04	0.03	0.04	80.9	80.9	80.9	0	0	0	AMAN
23:00:05	0.04	0.03	0.04	81.13	80.9	81.2	0	0	0	AMAN

http://sipalaga.brg.go.id