

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_621103\_02 LOKASI : BUKIT LITI 2

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:03	-0.39	-0.39	-0.39	40.1	40	40.3	0	0	0	SIAGA
01:00:00	-0.39	-0.4	-0.39	40.23	40.2	40.3	0	0	0	SIAGA
02:00:03	-0.39	-0.4	-0.39	40.3	40.3	40.3	0	0	0	SIAGA
03:10:01	-0.39	-0.4	-0.39	40.3	40.3	40.3	0	0	0	SIAGA
05:00:03	-0.39	-0.39	-0.39	40.1	40.1	40.1	0	0	0	SIAGA
11:30:02	-0.41	-0.41	-0.4	39.97	39.9	40	0	0	0	BAHAYA
12:00:04	-0.41	-0.41	-0.4	39.8	39.7	39.9	0	0	0	BAHAYA
13:10:01	-0.41	-0.41	-0.4	39.67	39.6	39.8	0	0	0	BAHAYA
14:00:01	-0.41	-0.41	-0.41	39.38	39.2	39.5	0	0	0	BAHAYA
15:00:00	-0.41	-0.41	-0.41	39.2	39.2	39.2	0	0	0	BAHAYA
16:00:01	-0.41	-0.41	-0.41	38.95	38.9	39.2	0	0	0	BAHAYA
17:00:03	-0.41	-0.42	-0.41	38.97	38.9	39.1	0	0	0	BAHAYA
18:00:04	-0.41	-0.41	-0.41	39.1	39.1	39.1	0	0	0	BAHAYA
19:00:01	-0.41	-0.42	-0.41	39.03	38.8	39.1	0	0	0	BAHAYA
20:00:03	-0.41	-0.41	-0.41	38.93	38.6	39.1	1	0	0.8	BAHAYA
21:00:03	-0.41	-0.41	-0.41	39	38.9	39.1	0	0	0	BAHAYA
22:00:03	-0.41	-0.42	-0.41	38.9	38.9	38.9	0.4	0	0.2	BAHAYA
23:00:01	-0.41	-0.41	-0.41	38.9	38.9	38.9	0.4	0	0.4	BAHAYA

http://sipalaga.brg.go.id