

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_627104\_02 LOKASI : TN SEBANGAU 2

**KECAMATAN: SABANGAU** 

KABUPATEN: KOTA PALANGKARAYA PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 14 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
04:10:02	0.75	0.75	0.75	78.3	78.3	78.3	0	0	0	AMAN
05:00:03	0.76	0.76	0.76	78.2	78.2	78.2	0	0	0	AMAN
07:40:03	0.76	0.76	0.76	77.7	77.5	77.9	0	0	0	AMAN
08:00:03	0.77	0.76	0.77	78.18	77.8	78.5	0	0	0	AMAN
09:00:02	0.77	0.77	0.77	78.3	78.3	78.3	0	0	0	AMAN
10:00:02	0.77	0.77	0.77	78.35	78.3	78.5	0	0	0	AMAN
11:00:01	0.77	0.77	0.77	78.1	77.6	78.4	0	0	0	AMAN
12:30:03	0.77	0.77	0.77	78.4	78.4	78.4	0	0	0	AMAN
13:00:01	0.77	0.76	0.77	78.5	78.4	78.6	0	0	0	AMAN
14:10:00	0.77	0.76	0.77	77.85	77.8	77.9	0	0	0	AMAN
16:10:03	0.77	0.76	0.77	77.95	77.9	78	2.2	0	2.2	AMAN
17:30:03	0.77	0.77	0.77	78	78	78	0	0	0	AMAN
18:30:03	0.76	0.76	0.76	78	78	78	0	0	0	AMAN
19:30:02	0.77	0.77	0.77	78	78	78	0	0	0	AMAN
20:00:03	0.77	0.76	0.77	78	78	78	0	0	0	AMAN
21:00:02	0.76	0.76	0.76	78	78	78	0	0	0	AMAN
22:40:04	0.76	0.76	0.76	78	78	78	0	0	0	AMAN

http://sipalaga.brg.go.id