

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_621103\_04 LOKASI : BUKIT RAWI

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 15 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:20:08	-0.01	-0.01	-0.01	70.8	70.8	70.8	0	0	0	SIAGA
01:10:00	-0.02	-0.04	-0.01	70.8	70.8	70.8	0	0	0	SIAGA
03:20:08	-0.01	-0.01	-0.01	70.9	70.9	70.9	0	0	0	SIAGA
04:00:28	-0.01	-0.01	-0.01	70.9	70.9	70.9	0	0	0	SIAGA
05:00:15	-0.01	-0.02	-0.01	71	70.9	71.2	0	0	0	SIAGA
06:00:02	-0.04	-0.05	-0.02	70.9	70.9	70.9	0.4	0	0.4	SIAGA
07:10:02	-0.02	-0.02	-0.02	71.06	70.9	71.1	0	0	0	SIAGA
08:00:38	-0.02	-0.02	-0.02	71	70.9	71.1	0	0	0	SIAGA
09:00:16	-0.02	-0.03	-0.02	70.9	70.9	70.9	0	0	0	SIAGA
10:00:06	-0.02	-0.03	-0.02	70.93	70.8	71	0	0	0	SIAGA
11:00:17	-0.03	-0.03	-0.02	70.78	70.6	71	0	0	0	SIAGA
13:00:02	-0.03	-0.03	-0.03	70.5	70.5	70.5	0.2	0.2	0.2	SIAGA
14:20:08	-0.03	-0.03	-0.03	70.5	70.4	70.7	0	0	0	SIAGA
15:30:26	-0.03	-0.03	-0.03	70.7	70.7	70.7	1	1	1	SIAGA
18:00:53	-0.02	-0.02	-0.02	70.6	70.6	70.6	0	0	0	SIAGA
20:40:07	-0.02	-0.02	-0.02	70.7	70.6	70.8	0	0	0	SIAGA
21:20:38	-0.03	-0.03	-0.02	70.8	70.8	70.8	0	0	0	SIAGA
22:00:06	-0.02	-0.02	-0.02	70.8	70.8	70.8	0	0	0	SIAGA

http://sipalaga.brg.go.id