

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : MUBA2
LOKASI : KEPAYANG
KECAMATAN : BAYUNG LENCIR
KABUPATEN : MUSI BANYUASIN

PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 22 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-4.46	-4.44	-4.47	37.52	34.67	41.71	0	0	0	ВАНАҮА
01:00:00	-4.46	-4.43	-4.47	40.22	37.82	42.66	0	0	0	BAHAYA
02:00:00	-4.46	-4.45	-4.47	41.18	40.34	41.87	0	0	0	BAHAYA
03:00:00	-4.46	-4.45	-4.48	42.3	41.16	44.93	0	0	0	BAHAYA
04:00:00	-4.45	-4.43	-4.46	44.45	42.85	48.05	0	0	0	BAHAYA
05:00:00	-4.44	-4.43	-4.46	45.69	43.84	48.56	0	0	0	BAHAYA
06:00:00	-4.45	-4.45	-4.46	44.34	43.61	45.79	0	0	0	BAHAYA
07:00:00	-4.45	-4.44	-4.47	46.13	44.13	49.79	0	0	0	BAHAYA
08:00:00	-4.47	-4.45	-4.49	45.27	43.25	49.24	0	0	0	BAHAYA
09:00:00	-4.49	-4.49	-4.5	43.58	42.49	44.76	0	0	0	BAHAYA
10:00:00	-4.51	-4.5	-4.52	40.64	39.24	42.23	0	0	0	BAHAYA
11:00:00	-4.5	-4.49	-4.51	39.12	37.21	43.05	0	0	0	BAHAYA
12:00:00	-4.51	-4.5	-4.52	35.83	33.99	37.76	0	0	0	BAHAYA
13:00:00	-4.51	-4.51	-4.52	34.51	33.76	35.29	0	0	0	BAHAYA
14:00:00	-4.52	-4.51	-4.52	33.55	32.59	34.35	0	0	0	BAHAYA
15:00:00	-4.52	-4.52	-4.52	32.73	32.73	32.73	0	0	0	ВАНАҮА

http://sipalaga.brg.go.id