

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : LUMPUR1 LOKASI : AS1R-RIDING

KECAMATAN: PANGKALAN LAPAM
KABUPATEN: OGAN KOMERING ILIR
PROVINSI: SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 01 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
01:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
02:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
03:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
04:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
05:00:00	-3.23	-3.23	-3.23	9.08	9.08	9.08	0	0	0	BAHAYA
06:00:00	-3.23	-3.23	-3.23	9.05	9.01	9.08	0	0	0	BAHAYA
07:00:00	-3.23	-3.23	-3.23	8.81	8.74	8.95	0	0	0	BAHAYA
08:00:00	-3.23	-3.23	-3.23	8.71	8.68	8.74	0	0	0	BAHAYA
09:00:00	-3.23	-3.23	-3.23	8.68	8.68	8.68	0	0	0	BAHAYA
10:00:00	-3.23	-3.23	-3.23	8.68	8.68	8.68	0	0	0	BAHAYA

http://sipalaga.brg.go.id