

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_621103\_06 LOKASI : BUKIT LITI 3

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI MINGGU, 10 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Otatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:03	0.15	0.15	0.15	70.7	70.7	70.7	0	0	0	AMAN
01:00:03	0.15	0.14	0.15	70.68	70.6	70.7	0	0	0	AMAN
02:10:03	0.14	0.14	0.14	70.68	70.6	70.9	0	0	0	AMAN
03:00:02	0.13	0.13	0.14	70.73	70.6	70.8	0	0	0	AMAN
04:00:02	0.13	0.13	0.14	70.8	70.8	70.8	0	0	0	AMAN
05:00:02	0.13	0.12	0.13	70.93	70.8	71	0	0	0	AMAN
06:00:02	0.12	0.12	0.13	70.95	70.9	71	0	0	0	AMAN
07:00:02	0.12	0.11	0.12	71	71	71	0	0	0	AMAN
08:00:02	0.11	0.11	0.12	70.96	70.9	71	0	0	0	AMAN
09:10:00	0.11	0.11	0.11	70.95	70.8	71	0	0	0	AMAN
10:20:02	0.1	0.1	0.11	71	71	71	0	0	0	AMAN
12:20:01	0.1	0.1	0.1	70.8	70.8	70.8	0	0	0	AMAN
13:00:02	0.1	0.09	0.1	70.73	70.6	70.9	0	0	0	AMAN
14:00:02	0.09	0.09	0.1	70.7	70.7	70.7	0	0	0	AMAN
15:10:04	0.09	0.09	0.09	70.4	70.3	70.5	0	0	0	AMAN
16:00:01	0.09	0.08	0.09	70.28	70.1	70.6	0	0	0	AMAN
17:00:02	0.08	0.08	0.08	70.1	70.1	70.1	0	0	0	AMAN
18:10:00	0.08	0.08	0.08	70.2	70.2	70.2	0	0	0	AMAN
19:00:01	0.08	0.08	0.09	70.2	70.2	70.2	0	0	0	AMAN
21:00:04	0.08	0.08	0.08	69.5	69.5	69.5	0	0	0	AMAN
22:00:03	0.08	0.08	0.08	69.3	69.3	69.3	0	0	0	AMAN

http://sipalaga.brg.go.id