

## BADAN RESTORASI GAMBUT

## REPUBLIK INDONESIA

STASIUN : BRG\_621103\_04 LOKASI : BUKIT RAWI

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI SELASA, 12 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ <sub>o</sub> )			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
10:00:10	-0.04	-0.04	-0.04	71.4	71.3	71.5	0	0	0	SIAGA
11:50:24	-0.04	-0.04	-0.04	71.3	71.3	71.3	0	0	0	SIAGA
13:20:11	-0.04	-0.04	-0.04	71.3	71.3	71.3	0	0	0	SIAGA
14:10:05	-0.04	-0.04	-0.04	71.3	71.3	71.3	0	0	0	SIAGA
15:40:20	-0.03	-0.03	-0.03	71.1	71.1	71.1	0	0	0	SIAGA
16:00:48	-0.03	-0.03	-0.03	71.32	71.1	71.4	0	0	0	SIAGA
17:00:16	-0.03	-0.03	-0.03	71.27	71.1	71.4	0	0	0	SIAGA
18:00:14	-0.04	-0.07	-0.03	71.16	71.1	71.4	0	0	0	SIAGA
19:20:31	-0.03	-0.03	-0.03	71.25	71.1	71.4	0	0	0	SIAGA
20:30:11	-0.03	-0.03	-0.03	71.3	71.3	71.3	0	0	0	SIAGA
21:20:02	-0.03	-0.03	-0.03	71.33	71.2	71.4	1.8	0.2	0.8	SIAGA
22:00:28	-0.03	-0.03	-0.03	71.35	71.3	71.4	0.8	0	0.8	SIAGA
23:20:20	-0.02	-0.02	-0.02	71.3	71.3	71.3	0.6	0.2	0.4	SIAGA

http://sipalaga.brg.go.id