

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140509_01 LOKASI : KUALA SEPANDUK KECAMATAN : TELUK MERANTI KABUPATEN : PELALAWAN

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI JUMAT, 15 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			0
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:09	-1.31	-1.32	-1.31	11.74	11.7	11.9	0	0	0	BAHAYA
01:00:06	-1.32	-1.32	-1.31	11.8	11.7	11.9	0	0	0	BAHAYA
02:00:01	-1.32	-1.32	-1.31	11.7	11.7	11.7	0	0	0	BAHAYA
03:00:03	-1.32	-1.33	-1.31	11.77	11.7	12	0	0	0	BAHAYA
04:00:08	-1.31	-1.32	-1.31	11.8	11.8	11.8	0	0	0	BAHAYA
05:40:02	-1.32	-1.32	-1.32	11.65	11.5	11.8	0	0	0	BAHAYA
06:30:04	-1.32	-1.32	-1.32	11.8	11.8	11.8	0	0	0	BAHAYA
07:30:07	-1.32	-1.32	-1.31	11.65	11.5	11.8	0	0	0	BAHAYA
08:00:07	-1.32	-1.32	-1.32	11.56	11.5	11.8	0	0	0	BAHAYA
09:00:39	-1.32	-1.33	-1.32	11.52	11.5	11.6	0	0	0	BAHAYA
10:00:03	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
11:20:45	-1.32	-1.33	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
12:10:05	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
13:00:39	-1.32	-1.33	-1.32	11.73	11.6	11.8	0	0	0	BAHAYA
14:00:03	-1.32	-1.33	-1.32	11.7	11.6	11.9	0	0	0	BAHAYA
15:00:03	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	BAHAYA
16:30:59	-1.32	-1.32	-1.32	11.6	11.6	11.6	0	0	0	ВАНАҮА
17:00:52	-1.32	-1.32	-1.32	11.7	11.6	11.9	0	0	0	ВАНАҮА
18:00:03	-1.32	-1.32	-1.32	11.54	11.5	11.6	0	0	0	ВАНАҮА
19:00:02	-1.32	-1.32	-1.32	11.55	11.5	11.6	0	0	0	ВАНАҮА
20:10:05	-1.32	-1.32	-1.32	11.6	11.5	11.8	0	0	0	ВАНАҮА
22:00:12	-1.32	-1.32	-1.32	11.54	11.5	11.6	0	0	0	ВАНАҮА
23:00:13	-1.32	-1.33	-1.32	11.5	11.5	11.5	0	0	0	BAHAYA

http://sipalaga.brg.go.id