

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621107_06 LOKASI : JABIREN 2 KECAMATAN : JABIREN RAYA KABUPATEN : PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI SENIN, 11 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
02:40:31	-0.35	-0.35	-0.35	59.3	59.3	59.3	0	0	0	SIAGA
07:20:17	-0.35	-0.35	-0.35	59.27	59.1	59.4	0	0	0	SIAGA
08:10:08	-0.35	-0.35	-0.35	58.95	58.7	59.2	0	0	0	SIAGA
10:10:21	-0.35	-0.35	-0.35	58.55	58.3	58.8	0	0	0	SIAGA
11:20:19	-0.36	-0.36	-0.36	58.4	57.7	59.4	0	0	0	SIAGA
12:40:09	-0.35	-0.35	-0.35	58.3	58.3	58.3	0	0	0	SIAGA
13:10:18	-0.35	-0.36	-0.35	57.83	57.5	58.1	0	0	0	SIAGA
14:30:40	-0.35	-0.36	-0.35	57.47	57.2	57.8	0	0	0	SIAGA
15:30:20	-0.35	-0.35	-0.35	57.4	57.4	57.4	0	0	0	SIAGA
17:40:04	-0.36	-0.36	-0.36	57.7	57.7	57.7	0	0	0	SIAGA
18:00:03	-0.36	-0.36	-0.36	57.9	57.7	58.1	0	0	0	SIAGA
19:00:03	-0.36	-0.36	-0.36	57.8	57.8	57.8	0	0	0	SIAGA
20:20:24	-0.37	-0.37	-0.37	57.9	57.9	57.9	0	0	0	SIAGA
21:10:01	-0.36	-0.37	-0.36	65.54	58.1	67.5	19.6	0	6.2	SIAGA
22:00:07	-0.34	-0.35	-0.34	67.65	67.5	67.8	0	0	0	SIAGA
23:10:42	-0.34	-0.34	-0.33	66.7	65.7	67.9	0.8	0.2	0.4	SIAGA

http://sipalaga.brg.go.id